

Instruction Manual

WP PCD 650

Waterproof Handheld pH/Cond/DO Meter



OAKTON®

EUTECH
INSTRUMENTS

Technology Made Easy...

ISO 9001
CERTIFIED

68X415307 Rev. 0 Feb 07

Preface

This manual serves to explain the use of the **Waterproof Handheld PCD 650 multi parameter Meter**. The manual functions in two ways, firstly as a step by step guide to help the user operate the instrument. Secondly, it serves as a handy reference guide. This instruction manual is written to cover many anticipated applications of the PCD 650 Meter. If you have doubts in the use of the instrument, please do not hesitate to contact the nearest Authorised Distributor.

The information presented in this manual is subject to change without notice as improvements are made, and does not represent a commitment on part of Eutech Instruments / Oakton Instruments.

Eutech Instruments/ Oakton Instruments cannot accept any responsibility for damage or malfunction of the unit due to improper use of the instrument.

Copyright ©2006 All rights reserved.

Eutech Instruments Pte Ltd.

Oakton Instruments

Table of Contents

1. Getting Started	1
1.1 About the Meter	1
1.2 Display & Keypad	2
1.2.1 Display Overview	2
1.2.2 Key Functions	3
1.3 Inserting Batteries	4
1.3.1 Inserting batteries for the first time	4
1.3.2 Changing batteries subsequently	5
1.3.3 Connecting DC Power adapter	5
1.4 Attaching Safety Belt	6
1.5 Connecting Peripherals	7
1.5.1 Probes (pH/Conductivity/DO)	7
1.5.2 Protective Rubber Boot	8
1.5.3 Multi Probe Holder	8
1.6 CyberComm 600 Data Acquisition Software	10
1.6.1 About CyberComm 600 DAS Application	10
1.6.2 Installing CyberComm 600	10
1.6.3 Starting CyberComm 600 for the first time	10
1.6.4 Connecting to the meter	12
2. Measurement Mode	15
2.1 About Measurement Mode	15
2.1.1 Accessing functions	15
2.2 Taking Measurement	17
2.2.1 Prepare the meter for measurement	17
2.2.2 Taking a reading	17
2.2.3 Stable reading indicator	17
2.2.4 Holding a reading	17
2.2.5 Automatic Temperature Compensation (ATC)	18
2.2.6 Manual Temperature Compensation (MTC)	18
2.2.7 Alarm set point (For pH/conductivity/DO)	18
2.2.8 Calibration Due (CAL-DUE) Indicator (For pH/conductivity/DO)	18
2.2.9 Resolution of pH Reading	18
2.2.10 pH buffer group for calibration and auto-recognition	18
2.2.11 pH Calibration points	19
2.2.12 Conductivity Calibration mode	19
2.2.13 Conductivity calibration points	19
2.2.14 Cell constant	19
2.2.15 Normalization Temperature (°C)	19
2.2.16 Linear temperature Coefficient	20
2.2.17 Pure Water Coefficient	20
2.2.18 Set Salinity	20
2.2.19 Auto Salinity Compensation	20
2.2.20 % Saturation Offset Adjustment	20
2.2.21 Set barometer pressure range and barometric pressure units	20
2.2.22 Pressure compensation	20
2.3 Multi Display mode	22
2.4 pH Measurement Mode	23
2.4.1 Indicators in pH measurement screen	23
2.5 mV Measurement Mode	24
2.5.1 Indicators in mV measurement mode	24
2.6 Ion Measurement Mode	25
2.6.1 Changing unit of measurement	25
2.6.2 Indicators in Ion measurement mode	25
2.7 Conductivity Measurement Mode	26
2.7.1 Indicators in Conductivity measurement screen	26

2.8	TDS Measurement Mode	27
2.8.1	Indicators in TDS measurement mode	27
2.9	Salinity Measurement Mode	28
2.9.1	Indicators in salinity measurement mode	28
2.10	Resistivity Measurement Mode	29
2.10.1	Indicators in Resistivity measurement mode	29
2.11	Percentage Saturation (%) Measurement Mode	30
2.11.1	Indicators in percentage saturation measurement mode	30
2.12	Concentration (mg/L) (ppm) Measurement Mode	31
2.12.1	Indicators in concentration measurement screen	31
2.13	Transfer Measured Data to Computer (CyberComm)	32
2.13.1	Sending a single reading from multi measurement mode	32
2.13.2	Sending a single reading from single measurement mode	33
2.13.3	Sending readings continuously in single and multi measurement modes	34
2.13.4	Saving data	35
2.14	Working with Memory functions	36
2.14.1	Logging data automatically in meter's memory	36
2.14.2	Storing currently displayed reading in the memory (In IrDA and LED print mode)	36
2.14.3	Viewing stored data	36
2.14.4	Transferring stored data to Computer (CyberComm) through IrDA	37

3. Calibration Mode39

3.1	About Calibration	39
3.1.1	About Temperature Calibration	39
3.1.2	About pH Calibration	39
3.1.3	About Ion Calibration	40
3.1.4	About Conductivity/Resistivity/TDS/Salinity Calibration	40
3.1.5	About DO(%) and DO (mg/L) Calibration	40
3.1.6	Prepare the Meter for Calibration	41
3.1.7	Accessing Calibration mode	42
3.1.8	Accessing Calibration mode when password protection enabled	42
3.2	Temperature Calibration	44
3.2.1	Temperature Calibration for ATC mode	44
3.2.2	Temperature Calibration for MTC mode	45
3.3	pH Calibration	46
3.3.1	pH Calibration with a Standard Buffer	46
3.3.2	pH Calibration with a User-defined Buffer	47
3.3.3	Calibration Report	48
3.3.4	Average Slope Indicator of pH Probe	49
3.4	mV Calibration	51
3.4.1	mV Calibration Report	52
3.5	Ion Calibration	53
3.5.1	Calibration Report	54
3.6	Conductivity Calibration	55
3.6.1	Manual Calibration	55
3.6.2	Automatic calibration (For Conductivity Calibration)	56
3.6.3	Calibration Report	58
3.7	Resistivity Calibration	59
3.7.1	Resistivity Calibration Report	60
3.8	Salinity Calibration	61
3.8.1	Salinity Calibration Report	62
3.9	TDS Calibration	63
3.9.1	TDS Calibration Report	64
3.10	DO Calibration in % Saturation Mode (with ATC)	65
3.10.1	To calibrate 100% saturation	65
3.10.2	To calibrate 0% saturation	67
3.10.3	% DO Calibration Report	67
3.11	DO Calibration in mg/L or ppm Concentration Mode	69
3.11.1	Concentration Calibration Report	70

4. Setup Mode	71
4.1 About Setup Mode	71
4.1.1 Accessing Setup mode (no password protection enabled)	71
4.1.2 Accessing Setup mode when password protection enabled	73
4.1.3 Modifying Setup parameters	74
4.2 System Setup	75
4.2.1 System Settings – Page 1	75
4.2.2 System Settings – Page 2	77
4.2.3 System Settings – Page 3	78
4.2.4 System Settings – Page 4	79
4.2.5 System Settings – Page 5	80
4.2.6 System Settings – Page 6	81
4.3 pH Setup	82
4.3.1 pH Settings – Page 1	82
4.3.2 pH Settings – Page 2	83
4.4 mV setup (no settings available)	84
4.5 Ion Setup	85
4.5.1 Ion Settings Page	85
4.6 Conductivity Setup	86
4.6.1 Conductivity Settings – Page 1	86
4.6.2 Conductivity Settings – Page 2	87
4.7 TDS Setup	88
4.7.1 TDS Settings – Page 1	88
4.7.2 TDS Settings – Page 2	89
4.8 Salinity Setup	90
4.8.1 Salinity Settings – Page 1	90
4.8.2 Salinity Settings – page 2	90
4.9 Resistivity Setup	92
4.9.1 Resistivity Settings – Page 1	92
4.9.2 Resistivity Settings – Page 2	92
4.10 O ₂ % - DO Saturation Setup	94
4.10.1 DO (%) – Page 1	94
4.10.2 DO (%) – Page 2	95
4.11 O ₂ mg/L (ppm) – DO Concentration Setup	96
4.11.1 DO (mg/L) – Page 1	96
4.11.2 DO (mg/L) – Page 2	97
4.12 Temperature Setup	98
4.12.1 Temperature Setting Page	98
5. Technical Specifications	99
6. Accessories	102
6.1 Replacement Accessories	102
6.2 Optional Accessories	102
7. APPENDIX	104
7.1 Conductivity theory	104
7.2 Calculating TDS Conversion Factor	106
7.3 Calculating Temperature Coefficients	106
7.4 Dissolved Oxygen Probe	107
7.4.1 Dissolved Oxygen Principle	107
7.4.2 Probe Care	107
7.4.3 Membrane Housing Replacement	108
7.4.4 Membrane/O-ring Replacement (Optional Procedure)	108
7.4.5 Electrolyte Solution	109
8. General Information	110
8.1 Warranty	110

8.2 Return of Goods 110

8.3 Guidelines for Returning Unit for Repair 110

1. Getting Started

1.1 About the Meter

Thank you for purchasing the PCD 650 waterproof multi parameter portable series meter. PCD 650 series meter are micro-controller based instruments and are designed with many user friendly features to measure up to 10 parameters including pH/ mV/ ISE/ Conductivity/ TDS /Salinity/ Resistivity/ DO (%)/ DO (mg/L)/ Temperature. **This meter can simultaneously measure and displays up to 2 parameters along with the temperature.**

PCD 650 measures pH range from -2.000 to 19.999 with accuracies up to ± 0.002 , mV (up to ± 2000) and Ion from 0.001 to 19900. pH calibration is capable of up to six calibration points and up to 15 buffer options with auto-buffer recognition of USA, DIN, NIST, and PWB standards.

This meter also measures conductivity (up to 500mS), Temperature (-10.0°C to 110.0°C) / units °C or ° F, Total Dissolved Solids (TDS) (up to 500ppt), Resistivity (up to 20.00M Ω) or Salinity (up to 80ppt) with either a 2- or 4-electrode conductivity cell. This meter also allows you to select cell constants, temperature coefficients, normalised temperature, TDS factor, calibration standard, points and temperature units.

PCD 650 also ensures accurate measurement of the Dissolved Oxygen values through its temperature, barometric pressure and salinity compensation features.

Special Features:

- Displays and measures up to 2 parameters simultaneously.
- Automatic temperature compensation.
- Large Monochrome graphic display with 110X128 resolution and viewing area of 68X74 mm.
- Powered by ARM7TDMI-S cored microcontroller.
- Built in memory backup to save calibration and 500 sets of measured data.
- Data logging feature date-and-time stamp to meet Good Laboratory Practice (GLP).
- One way serial data transmission through IrDA or RS232 through LED.
- Features user-selectable 'CAL-DUE' and set point alarm functions.
- Power source and Battery level indicator.
- Designed to work either from mains power or battery and automatically detect and switch to mains if available.
- Alkaline Battery can last for more than 200 Hours of continuous operation without Backlight and Serial data transferring.
- Water proof casing.
- User configurable password protection for calibration & setup data.

Useful hints will appear throughout the manual and on-screen to ease user during meter operation.

1.2 Display & Keypad

1.2.1 Display Overview

The large monochrome display shows detailed information about measurements, various indicators, annunciators, functions and useful tips. The display consists of 3 main sections when the meter is in the measurement mode:

- **Header** – Displays indicators for power source, battery level, pH probe condition, conductivity range of the probe, data transmission mode, real-time clock, user lock/unlock etc.
- **Body** – Displays measurement related information.
- **Footer** – Displays functions available for a given mode of operation. At any given time, up to four function names are displayed, that correspond to 4 function keys in the keypad. Left & Right arrow icons are displayed when there are more functions available than the 4-functions shown in the display. To access a function, press the corresponding function key (in keypad) just below the function name. To see other available functions, press left ◀ or right ▶ arrow key in the keypad.




Figure 1: Display

Indicators Used in Header Area





	Power Source & Battery Level: Battery, level 80%-90%		Conductivity range of the probe
	Power Source: DC Adapter		Average slope of the pH probe
	Data Transmission mode: LED		Current Time in 24 Hour format
	Data Transmission mode: Infrared		Password Protection: Disable
	Data Logging Mode: MEM		Password Protection: Enable

Refer **calibration mode**, **measurement mode** & **setup mode** for details on indicators shown in body & footer sections.

1.2.2 Key Functions

The keypad consists of:

- 4 – Function keys (F1, F2, F3 & F4)
- 4 – Navigation key
- 1 – Enter key

Key	Function
	<ul style="list-style-type: none"> ▪ Selects the function shown (in the display) just above the key.
	<ul style="list-style-type: none"> ▪ Navigates to next available functions
	<ul style="list-style-type: none"> ▪ Increment/decrement values in Setup & Calibration modes. ▪ Navigates to sub groups in Setup selection screen.
	<ul style="list-style-type: none"> ▪ In Setup mode, confirms selection or modified values ▪ In Calibration mode, confirms calibration points or modified values




Figure 2 : Display & Keypad

1.3 Inserting Batteries

The meter supports multi -power sources.

1. Four 'AA' size 1.5 V alkaline batteries (supplied) or,
2. 9V DC power adapter (Optional in some models).





Figure 3 : Battery compartment

1.3.1 Inserting batteries for the first time

1. Use a Phillips screw driver to remove four screws holding the battery cover.
2. Remove the battery cover.
3. Follow the polarity indicated in the battery compartment and insert the batteries.
4. Replace the battery cover onto its original position using the four screws. Note the **▲UP** symbol marked on the cover.
5. The meter is ready to operate. Use **ON (F4)** key to switch on the meter. The **ON (F4)** key has to be kept pressed until the display comes up.
6. Set the system date & time before you start operating the meter for the first time. Refer ' : System Settings - Page 2' in page 77 for details on how to set date & time.

1.3.2 Changing batteries subsequently

The LCD has battery voltage level indicator.  Number of bars indicates the voltage level. See Table 1 for details. When the empty battery indicator starts blinking, it is time to change the batteries.


The system time might be automatically reset during the battery change. To prevent that happening, always connect the DC adapter during battery change.

Alternatively, if the DC adapter is not available, switch **off** the meter and change the batteries within **30** seconds to avoid resetting the clock.

Number of Bars	Approximate battery voltage (V)
4	6.0 to 5.4
3	5.4 to 4.8
2	4.8 to 4.2
1	4.2 to 3.8
No bars (Empty battery blinks)	Below 3.8

Table 1 : Battery level indication

1.3.3 Connecting DC Power adapter

Connecting the DC adapter saves battery life. The power adapter indicator  appears in LCD when you connect the DC power adapter to the meter.




Figure 4 : Connecting DC power adapter

1.4 Attaching Safety Belt

The safety belt provides secured support when you hold the meter on your palm.

To attach the safety belt:

1. Use a Phillips screw driver to remove four screws holding the battery cover.
2. Remove the battery cover.
3. Insert the safety belt through the two slots as indicated in the Figure 5.
4. Replace the battery cover onto its original position using the four screws. Note the ▲UP symbol marked on the cover.
5. Insert your palm in between the belt and the body of the meter and adjust the hook & loop fastener.




Figure 5 : Attaching safety belt

1.5 Connecting Peripherals

1.5.1 Probes (pH/Conductivity/DO)

Attach the probes with correct type of connectors as indicated in the figure below.




Figure 6 : Connecting ph, Cond and DO Probes

The PCD 650 meters allows to connect a pH or ISE, DO and a conductivity probe at the same time. Two types of conductivity electrodes: the 2-cell conductivity cell and the 4-cell conductivity cell can be used with this meter and only one can be connected at a time. The meter can also adjust cell constant from 0.010 to 10.000. This electrode features a built-in temperature sensor for Automatic temperature compensation (ATC). It has a specially designed housing that provides fast temperature response and reduces air bubble entrapment, which makes it easy to obtain accurate, stable readings.

Proper use of electrode is essential to ensure that the optimum measurement is taken in a short time. The removable protective plastic electrode guard on the conductivity cell is meant for simple periodic maintenance and it must be kept in tact during measurement and calibration. Always immerse the electrode beyond upper steel band as shown in Figure 7. We recommend that you do not submerge the electrode above the protective yellow cap. You can submerge the cable for brief periods of time, but not continuously.

This meter uses a special notched 6-pin connector to attach the DO probe to the meter. The Dissolved Oxygen Probe works on galvanic principle, that is, it




Figure 7: Probe immersion level

does not require any polarizing voltage from your meter. The galvanic probe design lets you take measurements immediately – without the typical 15 minute wait of other dissolved oxygen probes.

The DO probe comes with an in-built Temperature Compensation for the membrane variation and consists of two parts. The upper part consists of an anode, a cathode, and cable, and lower part consists of a membrane cap, membrane, and electrolyte solution.

Be sure to remove the protective electrode storage bottle or rubber cap of the pH electrode before calibration or measurement. If the electrode has been stored dry, wet the electrode in clean water for 10 minutes before calibrating or taking readings to saturate the pH electrode surface and to minimize drift.

1.5.2 Protective Rubber Boot

The rubber boot protects the meter and gives a good hand grip. It is ideal when you use the meter in the field. For bench top applications, lift up the stand at the back of the rubber boot.




Figure 8 : Inserting/removing the rubber boot

1.5.3 Multi Probe Holder

Multi probe holder provides a convenient means to hold pH, conductivity and DO probes together. Refer 'Figure 9: Using multi probe holder' on page 9 to know how to assemble electrodes (pH, conductivity and DO) into the electrode holder.

1. Insert pH and Conductivity electrodes one at a time from outside in through the electrode cover.
2. Clip DO electrode into the holder as shown in Figure 9.

3. Insert the probes into the multi probe holder as shown in Figure 9. After assembling the electrodes into the electrode holder, ensure that the electrode top surfaces are almost level to the edges of the holder.
4. Align the markings on the holder and the cover before locking the cover onto the holder as shown in the diagram.
5. Push up the electrodes backwards to fix the vertical position of the electrodes into the electrode cover. **Note:** For pH electrode, the storage solution has to put back after assembling the electrodes.
6. To remove the cover, hold onto the electrodes with one hand and release any two catches from the side of the cover with the other hand as indicated in figure.




Figure 9: Using multi probe holder

Note: All our conductivity probes have built-in ATC probes. It can also be used for temperature readout and compensation of the pH values. Therefore, there is no need to install a separate ATC probe for pH.

1.6 CyberComm 600 Data Acquisition Software

1.6.1 About CyberComm 600 DAS Application

The PCD 650 series meters are shipped with a companion software application called **CyberComm 600 Data Acquisition Software (DAS)**. This is a simple, easy to use, Windows® based PCD compatible software application which lets you download your measurement data, calibration reports & stored data from the PCD 650 series meters and save them in your PCD in text (.txt) files. It automatically recognizes meter's model number once the connection is established. This software is designed to display data for both single and multi parameter models.

CyberComm DAS communicates with the meter through wireless IrDA connection. You need to have a PC or Notebook running Windows® 2000 or Windows® XP with an IrDA port or with USB-IrDA dongle (not supplied) installed into the USB port of your PCD.

1.6.2 Installing CyberComm 600

Make sure to log in to your computer with administrator user account. Insert the supplied software CD into the CDROM drive of your computer. The installation wizard should automatically start. Follow the screen instructions and complete the installation.

The software installs CyberComm 600 icon on Desktop and Start menu shortcut at 'Start > Programs > PC Communication > CyberComm 600'.



1.6.3 Starting CyberComm 600 for the first time




1. Double-click on the **CyberComm 600** icon available in the Desktop.
2. CyberComm 600 application starts. The screen lists connection procedure.
 - Switch on the meter. Make sure that the following settings have been configured in System Settings of the meter Setup. (Refer Figure 71: System Settings - Page 4' on page 79 for more details.)
 - PRINT MODE : IrDA
 - DATA FORMAT: CyberComm
 - CURRENT DATA SET: TIMED
 - Make sure the IrDA port of the meter is closer and pointing towards (line-of-sight with) the IrDA port (or USB-IrDA dongle) of the computer.
 - From measurement mode, press left  or right  arrow key until you see **PRIN** function in the display.
 - Press **PRIN (F3)** key. IrDA data communication icon  starts animating as the meter sends data to computer through IrDA.
3. The Computer recognizes the PCD 650 series meter and you will see 'Found New Hardware' message in the Taskbar. (Figure 10)



Figure 10 : Computer recognizes the meter

4. The 'Found New Hardware Wizard' starts automatically. Select '**Yes, this time only**' option for the first screen. (Figure 11) .Click **Next** to continue.



Figure 11 : First screen of 'Found New Hardware Wizard'

5. In the second screen (Figure 12), select '**Install the software automatically (Recommended)**' and click **Next** to continue.




Figure 12 : First screen of 'Found New Hardware Wizard'

6. Once the wizard completed the installation (Figure 13), click **Finish** to close the wizard.




Figure 13 : 'Found New Hardware Wizard' completed

7. In CyberComm 600 application screen, click **Find Device** button. The screen shows a message "Finding device". When CyberComm recognizes the meter it shows "Instrument in Range, click Connect button to establish connection..."

Note: If you do not see the above message, re-position the IrDA port of the meter with IrDA port of computer so that they become close to each other and are in-line.

8. Click **Connect** button. Once the connection is established, the measurement data sent by the meter is shown in the CyberComm screen.

1.6.4 Connecting to the meter

Once you successfully established the connection between the meter and CyberComm, for the first time, as described in the above section, the subsequent connections will be established in a few easy steps.

Follow the steps below to connect CyberComm to the meter:


1. Start CyberComm by double-clicking on **CyberComm 600** Desktop icon. Make sure the IrDA port of the meter is closer and pointing towards (line-of-sight with) the IrDA port (or USB-IrDA dongle) of the computer.
2. In the meter, press **PRIN (F3)** key. IrDA data communication icon  starts animating as the meter sends data to computer through IrDA.
3. In CyberComm, press **Find Device** button.



Figure 14 : CyberComm finds the meter

4. When CyberComm recognizes the meter it shows “Instrument in Range, click Connect button to establish connection...” Press **Connect** button.




Figure 15 : CyberComm establishing connection with the meter

5. The connection is established and data is transferred.

Notes:

The communication between CyberComm and the meter is uni-directional. The connection is initiated by the meter when you press **PRIN** key. Once CyberComm finds the meter, press **Connect** button. Once the connection is established the data is transferred to CyberComm and then the IrDA link is disconnected automatically. IrDA link is disconnected after sending single set of data only if 'SINGLE' is selected from System Setup (page 78).

- To re-establish the connection, you need press **PRIN** key of the meter followed by **Connect** button from CyberComm.
- For continuous transfer of measurement readings, set CURRENT DATA SET parameter to 'TIMED' in System Setup (page 78).
- For single transfer of measurement reading, set CURRENT DATA SET parameter to 'SINGLE' in System Setup (page 78)

2. Measurement Mode

2.1 About Measurement Mode

Following measurement modes are available in PCD 650 models:

- pH measurement mode
- mV measurement mode
- Ion measurement mode
- Conductivity measurement mode
- TDS measurement mode
- Salinity measurement mode
- Resistivity measurement mode
- O₂ % - DO percentage saturation measurement mode
- O₂ mg/L(ppm) - DO concentration mode

When powered-on, the meter goes to any of the above measurement modes, depending on the last selected measurement mode, before the meter was powered-off. For instance, the meter starts with TDS measurement mode, if the meter was in TDS measurement mode, when you last switched off the meter. Press **MODE (F3)** key to switch between above measurement modes.

2.1.1 Accessing functions

There are many functions available in the measurement mode. You can use the 4-function key to access them. These functions are grouped into 4 to share the available 4-function keys. The first group appears when you enter the measurement mode. Press left ◀ or right ▶ arrow key to navigate to 2nd and 3rd function groups.




Figure 16 : Use Left ◀ or Right ▶ arrow keys to navigate between function groups

Function Keys available in measurement screen (1st Group):

HOLD (F1) Holds the current reading in the display. The 'HOLD' indicator starts blinking. Press HOLD key again to release the reading

CAL (F2) Goes to corresponding calibration mode (based on the selected measurement mode)

MODE (F3) Switches between measurement modes



OFF (F4) Power off the meter (press and hold this key for 3 seconds)

◀ ▶ Switches between functions groups available in measurement mode

ENTER (Not functional)

▲ ▼ (Not functional)

Function Keys available in measurement screen (2nd Group):**SETP (F1)** Goes to setup mode**MEM (F2)** Shows stored data in the memory**STOR (F3)** Stores the currently displayed reading in the memory**ESC (F4)** Shows 1st Group of functions**Function Keys available in measurement screen (3rd Group):****REPO(F2)** Shows corresponding calibration report (based on selected measurement mode)**PRIN (F3)** Sends the currently displayed reading to the computer through IrDA. (This key has to be pressed to establish communication with CyberComm PCD application through IrDA). If data logging mode has been selected in System Setup then it sends data automatically to meter's memory.**ESC (F4)** Shows 1st Group of functions

Note: If you press a function key that is not relevant to measurement mode (for example ENTER, , ) the meter shows 'Invalid key!' message in the footer area of the screen as shown in diagram.

**Figure 17: Invalid key**

2.2 Taking Measurement

2.2.1 Prepare the meter for measurement

Before you start measuring,

- Make sure you have connected a suitable probe (pH/OPR/ISE), Conductivity probe and DO with in-built ATC to the meter.
- Make sure the probes are in good working condition & clean. If required, clean (pH/OPR/ISE) probe with clean water, conductivity and DO probe with de-ionized water to remove impurities. For more information on probe's conditioning refer page 7.
- Make sure batteries have been installed or the DC adapter is connected to the meter.
- Perform calibration if you change to a new probe.

2.2.2 Taking a reading

1. Press **ON (F4)** key to switch on the meter. The **ON (F4)** key has to be kept pressed until the display comes up.
2. Make sure you are in the required measurement mode. Press **MODE (F3)** to switch between modes.
3. Dip the appropriate probe with built in ATC probe into the sample solution.

Note: When dipping the probe into sample, the sensor or the glass bulb of the probe must be completely immersed into the sample. Stir the probe gently in the sample to create a homogeneous sample. Allow time for the reading to stabilize.

4. The LCD shows '**Stable**' indicator if this feature is enabled in setup. (See page 75).
5. Note the reading.

2.2.3 Stable reading indicator

You can configure the meter so that LCD displays a '**Stable**' indicator when the reading does not vary for 2 consecutive seconds. The amount of variations allowed can be set as 'Slow', 'Medium' or 'Fast'. (See page 75)

2.2.4 Holding a reading

In some situations, you may want to freeze (hold) the measured reading in the LCD for a delayed observation. You can hold a reading in two different ways.

Manual Hold – Allows you to hold the reading by pressing **HOLD (F1)** key at any time you want. When you hold a reading, the '**HOLD**' indicator starts flashing. The readings (including temperature reading) will be held until you press any other key again.

Auto-Hold –The meter automatically holds the reading if the reading is '**Stable**' for 5 consecutive seconds. This feature needs to be enabled in the setup (See page 75). Press **HOLD (F1)** key to release the reading.

2.2.5 Automatic Temperature Compensation (ATC)

Connect an appropriate probe with built in ATC probe to the meter and select 'ATC mode' in the temperature setup (See page 98) for the pH/conductivity/DO reading to be automatically compensated for temperature variations.

If you select 'ATC' without connecting a probe to the meter, the LCD shows 'UNDER' for temperature reading.




Figure 18: Under range

NOTE: The factory default value for normalization temperature is 25 °C.

2.2.6 Manual Temperature Compensation (MTC)

If ATC probe is not available, you can choose to manually compensate for temperature. This is suitable when the temperature of your sample is sufficiently stable. Select 'MTC mode' in the temperature setup (see page 98). Press **CAL (F2)** and then press **NEXT** key. Press **TEMP (F1)** to go to temperature calibration. Enter the temperature value of your sample. See page 45 for more details on temperature calibration.

2.2.7 Alarm set point (For pH/conductivity/DO)

You can set the meter to display an alarm when the pH/conductivity/salinity/resistivity/TDS/DO(%) /DO(mg/L) reading goes higher or lower than predefined set points. Refer Setup of respective modes to set alarm points for pH, conductivity and DO.




Figure 19 : Hi alarm

2.2.8 Calibration Due (CAL-DUE) Indicator (For pH/conductivity/DO)

You can set a reminder to be displayed in the LCD when the next calibration is due. Set the number of days in the pH/conductivity/DO Setup and the meter will remind you when the days elapse from your last calibration date.

2.2.9 Resolution of pH Reading

By default, the resolution is set to 0.00. You can change the resolution in the setup mode. pH resolution can be adjusted from 0.1 to 0.001 pH (See page 83)

2.2.10 pH buffer group for calibration and auto-recognition

This option allows you to choose buffer group from four internationally recognized standard buffer groups namely USA, NIST, DIN & PWB. The default buffer group is USA. Refer 'pH Setup' section in page 82 for information on how to set the meter to a particular buffer group.

2.2.11 pH Calibration points

This option allows you to calibrate up to 6 points, depending on the standard buffer selected. Optionally, you can choose to have custom buffers with 2 to 5 points. When completely re-calibrating the meter, the first point of calibration should be one of the following, depending on your choice of standard buffer group. The meter automatically recognizes and calibrates to the standard pH buffer values, which makes pH calibration faster and easier.

2.2.12 Conductivity Calibration mode

This option allows you to select automatic or manual calibration standard. In the automatic calibration mode, the meter automatically detects and verifies the appropriate known calibration standards solutions before accepting these particular calibration standards as one of its calibration values in a specific measurement range. **Standard buffer values: 84.0 uS/ 1.413 mS/ 12.88 mS/ 111.8 mS**

In the manual calibration, non-standard calibration values can be used for calibration. You can manually input the appropriate values as your desired calibration standards in each specific range. The selected calibration standard will be displayed in the bottom of screen. Refer Figure 20.

2.2.13 Conductivity calibration points

This option allows you to select single or multi point calibration. Single point calibration refers to calibrating one conductivity value and uses it for the entire 5 conductivity ranges. In multi point calibration, you can calibrate one point in each of the measuring ranges (up to 5 points). The selected calibration point will be displayed in the bottom of screen. For example: If single point calibration is selected it will display 'SPC' in the bottom of screen as shown in diagram.




Figure 20 : Calibration standard & point indicator

But if a multi-point calibration option (calibration for different ranges is indicated in the Technical Specifications table on page 99) is chosen, calibration factors are applied only to their respective ranges.

2.2.14 Cell constant

This option lets you to adjust cell constant of the conductivity cell that you are using. Cell constant can be adjusted from 0.010 to 10.000. Please refer table on page 106 that lists the optimum conductivity ranges for electrodes with cell constants of 0.1, 1, and 10.

2.2.15 Normalization Temperature (°C)

This option will allow you to select a normalized temperature that the meter will use to normalize its conductivity measurements to a standard temperature.

NOTE: The factory default value for normalization temperature is 25 °C.

2.2.16 Linear temperature Coefficient

The temperature coefficient is a value that reflects the degree to which the conductivity is affected by temperature changes. If you do not know the temperature coefficient of your solution you can determine the correct value using the formula on page 106 “Calculating Temperature Coefficients”.

NOTE: Your meter is factory set to a temperature coefficient of 2.1% per °C.

2.2.17 Pure Water Coefficient

Pure water coefficient will be calculated and applied automatically for ultra pure water measurement if **‘ENABLE’** at appropriate set up pages.

For more information regarding pure water coefficient, please refer page 86.

2.2.18 Set Salinity

This option allows you to set the salinity (in ppt) for your solution, as the dissolved salts alter the relationship between the partial pressure of oxygen and the oxygen concentration in water. By setting the salinity, the meter will compensate for the impact of salinity on the partial pressure/oxygen concentration relationship of your sample. The salinity can be set from 0 to 50 ppt.

2.2.19 Auto Salinity Compensation

If auto salinity comp. is enabled, the meter will automatically compensate for salinity for determining dissolved oxygen concentration of the sample. Auto salinity compensation will be applicable only in multi measurement mode and only if one of the measurement selected is conductivity related. **This option is activated only in CD650 & PCD650.** Otherwise, manually set salinity value will be applied.

2.2.20 % Saturation Offset Adjustment

This option lets you offset meter's value when cross referenced with another DO meter. The PCD 650 meter allows to adjust % saturation offset calibration within +/- 10.0% offset.

Note: When a user calibration is done, the offset will be reset to zero.

2.2.21 Set barometer pressure range and barometric pressure units

The PCD 650 meter is capable of measuring barometric pressure with its built-in pressure sensor. In the event, the pressure reading is inaccurate, you can calibrate the value from the setup menu. For setting barometric pressure range, please refer page 94.

2.2.22 Pressure compensation

If pressure comp. is set to **‘ENABLE’**, the meter will compensate for the barometric pressure at the location depending on the altitude.

For example, if the barometric pressure is 700 mmHg the full scale calibration would be done at 92.1%. This is relative to the pressure at sea level.

If the pressure comp. is set to 'DISABLE', then there would be no compensation for the pressure. The calibration would be done at 100% irrespective of the altitude.

Note: This is applicable only for the % Saturation mode. For mg/L or ppm mode, pressure compensation would always be applicable.

2.3 Multi Display mode

PCD 650 lets you view multi measurement modes at the same time. The measurement modes available for PCD 650 are pH/ mV/ Ion/Conductivity/Salinity/Resistivity/TDS/ DO(%)/DO (mg/L). The parameters being displayed is based on the settings set in the Display Setup. For more information on multi mode setup, refer 'System Settings – Page 1' on page 75 to select modes that you would like to appear on the first, second and third row of the display.

Besides displaying the selected range, the meter also simultaneously displays the temperature. The user can also set the meter to display temperature in the multi measurement screen from in-built temperature of the COND & DO probes in the system setup screen. (Refer 'System Settings – Page 1' on page 75 to set temperature display)

In multi measurement screen, the lower display shows the temperature reading and the measurement mode (from where the temperature is selected in system setup). To display temperature from available modes, refer Page 75.




Figure 21: Multi measurement screen

Refer respective measurement modes to get detail information on the indicators and function keys that appear on the multi measurement screen.

For directions on how to calibrate your meter:

- See section 3.2 for Temperature calibration.
- See section 3.3 for pH calibration.
- See section 3.4 for mV calibration.
- See section 3.5 for Ion calibration.
- See section 3.6 for Conductivity calibration.
- See section 3.7 for Resistivity calibration.
- See section 3.8 for Salinity calibration.
- See section 3.9 for TDS calibration.
- See section 3.10 for DO(%) calibration.
- See section 3.11 for DO (mg/L) calibration.

2.4 pH Measurement Mode

2.4.1 Indicators in pH measurement screen

In pH measurement mode, the meter displays pH and temperature reading.




Figure 22 : pH measurement screen

Refer item numbers indicated in Figure 22.

Item	Description	More Details On
1	Measurement mode indicator	-
2	Appears when the reading is stable	Page 17, 75
3	Appears when the reading is on hold	Page 17, 75
4	pH reading	
5	Units of measurement	-
6	Temperature reading & units	Page 98
7	Temperature compensation mode	Page 18, 98
8	pH HI & LO Alarm limits	Page 82
9	pH Alarm indicator	Page 18, 82
10	Calibration Due indicator	Page 18, 83
11	Response time of the pH probe	Page 75
12	Calibrated Points	Page 19, 82

2.5 mV Measurement Mode

In mV measurement mode, the meter displays mV and temperature reading. Depending on application, you can connect a suitable ORP probe to the meter or use the pH probe.

2.5.1 Indicators in mV measurement mode




Figure 23 : mV measurement screen

Refer item numbers indicated in Figure 23.

Item	Description	More Details On
1	Measurement mode indicator	-
2	Appears when the reading is stable	Page 17, 75
3	Appears when the reading is on hold	Page 17, 75
4	mV reading	-
5	Units of measurement	-
6	Temperature reading & units	Page 98
7	Temperature compensation mode	Page 18, 98

Note: If offset is not zero, the meter displays relative mV reading of the solution in measurement mode.

2.6 Ion Measurement Mode

In Ion measurement mode, the meter displays Ion concentration (in ppm, molar or mg/L) and mV reading. Depending on application, you can connect a suitable Ion Selective Electrode (ISE) to the meter.

2.6.1 Changing unit of measurement

By default the measuring unit is ppm. You can select either molar or mg/L in the setup mode (See page 85).

2.6.2 Indicators in Ion measurement mode




Figure 24 : Ion measurement screen

Refer item numbers indicated in Figure 24.

Item	Description	More Details On
1	Measurement mode indicator	-
2	Appears when the reading is stable	Page 17, 75
3	Appears when the reading is on hold	Page 17, 75
4	Ion reading	-
5	Units of measurement	Page 85
6	mV reading	-

Note: If ion calibration has not been done, the display shows '- - -'.

2.7 Conductivity Measurement Mode

In conductivity measurement mode, the meter displays conductivity and temperature readings. The LCD shows related information for the conductivity measurement such as temperature compensation mode, stable indicator, probe condition, calibration points, response time of the conductivity probe and conductivity alarm conditions. You can customize or enable/disable some of these indicators in the Setup mode.

2.7.1 Indicators in Conductivity measurement screen




Figure 25 : Conductivity measurement screen

Refer item numbers indicated in Figure 25.

Item	Description	More Details On
1	Measurement mode indicator	-
2	Appears when the reading is stable	Page 17,75
3	Appears when the reading is on hold	Page 17, 75
4	Conductivity reading	-
5	Units of measurement	-
6	Temperature reading & units	Page 98
7	Temperature compensation mode	Page 18, 98
8	Conductivity HI & LO Alarm limits	Page 87
9	Conductivity Alarm indicator	Page 18, 87
10	Calibration Due indicator	Page 18, 86
11	Response time of the CON probe	Page 75
12	Conductivity ranges	Page 19
13	No of calibration points and method of calibration	Page 19, 86

2.8 TDS Measurement Mode

In TDS measurement mode, the meter displays TDS and temperature reading.

2.8.1 Indicators in TDS measurement mode




Figure 26 : TDS measurement screen

Refer item numbers indicated in Figure 26.

Item	Description	More Details On
1	Measurement mode indicator	-
2	Appears when the reading is stable	Page 17, 75
3	Appears when the reading is on hold	Page 17, 75
4	TDS reading	-
5	Units of measurement	-
6	Temperature reading & units	Page 98
7	Temperature compensation mode	Page 18, 98
8	TDS HI & LO Alarm limits	Page 18, 89
9	TDS Alarm indicator	Page 18, 89
10	Response time	Page 48
11	Calibration Due indicator	Page 18, 88
12	No of calibration points and method of calibration	Page 19, 88

Note: The factory default setting for the TDS conversion factor is 0.50. If your solution has a different TDS factor, you can improve calibration accuracy by setting the TDS factor prior to calibration. After setting the correct TDS Factor, you can commence calibration in the TDS mode. For more information regarding TDS conversion factor determination, please refer to page 106.

2.9 Salinity Measurement Mode

In Salinity measurement mode, the meter displays salinity and temperature reading.

2.9.1 Indicators in salinity measurement mode




Figure 27 : Salinity measurement screen

Refer item numbers indicated in Figure 27.

Item	Description	More Details On
1	Measurement mode indicator	-
2	Appears when the reading is stable	Page 75
3	Appears when the reading is on hold	Page 17, 75
4	Salinity reading	-
5	Units of measurement	-
6	Temperature reading & units	Page 98
7	Temperature compensation mode	Page 18, 98
8	Salinity HI & LO Alarm limits	Page 90
9	Salinity Alarm indicator	Page 18, 90
10	Response time	Page 48
11	Calibration Due indicator	Page 18, 90
12	No of calibration points and method of calibration	Page 19, 90

2.10 Resistivity Measurement Mode

In Resistivity measurement mode, the meter displays resistivity and temperature reading.

2.10.1 Indicators in Resistivity measurement mode




Figure 28 : Resistivity measurement screen

Refer item numbers indicated in Figure 28.

Item	Description	More Details On
1	Measurement mode indicator	-
2	Appears when the reading is stable	Page 75
3	Appears when the reading is on hold	Page 17, 75
4	Resistivity reading	-
5	Units of measurement	-
6	Temperature reading & units	Page 98
7	Temperature compensation mode	Page 18, 98
8	Resistivity HI & LO Alarm limits	Page 92
9	Resistivity Alarm indicator	Page 18, 92
10	Response time	Page 48
11	Calibration Due indicator	Page 18, 92
12	No of calibration points and method of calibration	Page 19, 92

2.11 Percentage Saturation (%) Measurement Mode

In percentage saturation measurement mode, the meter displays % saturation and temperature reading. The LCD shows related information for the saturation measurement such as temperature compensation mode, stable indicator, barometric pressure, calibration points, probe condition, response time of the DO probe and alarm conditions. You can customize or enable/disable some of these indicators in the Setup mode.

2.11.1 Indicators in percentage saturation measurement mode




Figure 29 : Percentage saturation measurement screen

Refer item numbers indicated in Figure 29.

Item	Description	More Details On
1	Measurement mode indicator	-
2	Appears when the reading is stable	Page 17, 75
3	Appears when the reading is on hold	Page 17, 75
4	Saturation reading	-
5	Units of measurement	-
6	Temperature reading & units	Page 98
7	Temperature compensation mode	Page 18, 98
8	Saturation HI & LO Alarm limits	Page 18, 95
9	Alarm indicator	Page 18, 95
10	Barometric pressure	Page 20, 94
11	Calibration points	Page 65

2.12 Concentration (mg/L) (ppm) Measurement Mode

In concentration measurement mode, the meter displays concentration and temperature readings. The LCD shows related information for the concentration measurement such as temperature compensation mode, stable indicator, salinity value, probe condition, response time of the DO probe and alarm conditions. You can customize or enable/disable some of these indicators in the Setup mode.

2.12.1 Indicators in concentration measurement screen




Figure 30 : Concentration measurement screen

Refer item numbers indicated in Figure 25.

Item	Description	More Details On
1	Measurement mode indicator	-
2	Appears when the reading is stable	Page 17, 75
3	Appears when the reading is on hold	Page 17, 75
4	Concentration reading	-
5	Units of measurement	Page 96
6	Temperature reading & units	Page 18
7	Temperature compensation mode	Page 18, 98
8	HI & LO Alarm limits	Page 18, 97
9	Alarm indicator	Page 18, 97
10	ppt indicator for input of salinity value	Page 96
11	DO calibration point	-

2.13 Transfer Measured Data to Computer (CyberComm)

2.13.1 Sending a single reading from multi measurement mode

1. Make sure that the **CURRENT DATA SET** parameter is set to 'SINGLE' in the System Setup (Refer 'System Settings – Page 4' on page 79).
2. Make sure the **CyberComm 600** application is up and running (page 12).
3. Make sure the IrDA port of the meter is closer and in-line with IrDA port of the computer.
4. From multi measurement mode, press **PRIN (F3)** to send data to CyberComm.
5. In CyberComm screen, press **Find Device** button. CyberComm starts finding the meter.
6. When CyberComm finds the meter, press **Connect** button. The IrDA link is established. The currently displayed measurement reading is transferred to CyberComm. (Figure 31)
7. Select **Row 1 data, Row 2 data or Row 3 data** from below there respective modes for which you wish to transfer data.
8. Once the data transfer is completed, the IrDA link is disconnected automatically.
9. To send another reading, repeat step 3, 4, 5 & 6.




Figure 31 : Transferring a single measurement data (Multi measurement mode)

2.13.3 Sending readings continuously in single and multi measurement modes

1. Make sure that the CURRENT DATA SET parameter is set to 'TIMED' in the System Setup. Set the time interval at which you wish to send the data to CyberComm (Refer 'System Settings – Page 4' on page 79).
2. Make sure the **CyberComm 600** application is up and running (page 12).
3. Make sure the IrDA port of the meter is closer and in-line with IrDA port of the computer.
4. From measurement mode, press **PRIN (F3)** to send data to CyberComm.
5. In CyberComm screen, press **Find Device** button.
6. When CyberComm finds the meter, press **Connect** button. The IrDA link is established. The measurement readings are sent to CyberComm continuously at the specified time interval as long as IrDA link is not disconnected. The transferred readings are displayed in the CyberComm screen (Figure 33).
7. To stop data transfer, click **Disconnect** button.
8. To clear the transferred readings in single measurement mode, click **Clear Data** button. To clear data in multi measurement mode, select the desired row and click **Clear Data** button.




Figure 33 : Transferring measurement data continuously

Note: IrDA link may be disconnected if you move/disorient the IrDA ports during data transfer. Re-align the IrDA ports and press **Connect** button, to re-establish the connection.

2.13.4 Saving data

You can save transferred measurement readings as a text file in your computer. Optionally, these text files can further be analyzed by exporting to spreadsheet application such as Microsoft® Excel.

To save data:

1. Once you transferred data to CyberComm, click **Disconnect** button. (if CyberComm is still connected to the meter)
2. Click **Save Data** button. **User Details** dialog appears to capture user information, file name and additional notes (if any). (Figure 34)




Figure 34 : User Details dialog

3. Enter your name & company name.
4. In **Storage Location**, specify a folder & file name with **.txt** extension.
 - Click **Browse** button. **Save As** dialog appears. Select a folder and specify a name for the file in **File name** field. Make sure you type **.txt** at the end of the file name.
 - If you simply type a file name (example: 'conductivity readings.txt') in the **Storage Location**, the file is saved in the installation folder of CyberComm.

Optionally, you may enter any notes or additional information in the **Notes** field.

5. Click **OK** button to save the data in the specified location/file.

Note: You can open and view the saved file using Windows® Notepad. You need to exit CyberComm before you can open the saved file.

2.14 Working with Memory functions

The PCD 650 has a memory capacity to store up to 500 sets of measurement data. The **MEM (F2)** function key allows you to view stored data. Optionally, you can transfer this data to a Computer using wireless Infrared connection.

2.14.1 Logging data automatically in meter's memory

1. Make sure that the Print mode is set to data logging mode in the System Setup and you can also specify the time interval in between each transfer. (Refer: 'System Settings – Page 4' on page 79)
2. From measurement mode, press **PRIN (F3)** to start saving data automatically in meter's memory. The memory location of the transferred reading is shown in the bottom-left of the screen. (Figure 35)








Figure 35 : Saving a reading

2.14.2 Storing currently displayed reading in the memory (In IrDA and LED print mode)

1. Make sure you are in the measurement mode.
2. Press left  or right  arrow key to navigate to other available functions until you see **STOR** function in the LCD.
3. Press **STOR (F3)** key to store the currently displayed reading. The display briefly shows the memory location where this reading is being saved. (Figure 35)

2.14.3 Viewing stored data

1. Make sure you are in measurement mode.
2. Press left  or right  arrow key to navigate to other available functions until you see **MEM** function in the LCD.

3. Press **MEM (F2)** key to view stored data. The last stored data entry is shown in the display (Figure 36). The memory location of the currently showing data entry is shown in the top-right corner of the screen. (Figure 36).




Figure 36 : Viewing stored data

4. To navigate to a particular memory location, press up ▲ or down ▼ arrow key to select memory location you intend to navigate to and then press **ENTER** key. The meter shows the stored data in the memory location you selected.
5. Press **NEXT (F3)** key to return to measurement mode from where you entered to view memory.
6. Press **ESC (F4)** key to return to main screen of the measurement mode.

2.14.4 Transferring stored data to Computer (CyberComm) through IrDA

1. Make sure the **CyberComm 600** application is up and running (page 12).
2. Make sure the IrDA port of the meter is closer and in-line with IrDA port of the computer.
3. Go to 'stored data viewing' screen as described in above section (Figure 36).
4. Press **PRIN (F2)**. The screen appears for you to select printing options (Figure 37). This allows you to choose either all memory locations or the current memory location for transfer.
5. Press up ▲ or down ▼ arrow key to select your choice and then press **ENTER** key.
6. If you have selected 'All locations', then you can specify the time interval in between each transfer. Press up ▲ or down ▼ arrow key to select time interval (1 to 50 seconds) and press **ENTER** key.
7. In CyberComm screen, press **Find Device** button.
8. Once CyberComm finds the meter, click **Connect** button to establish connection.

9. The CyberComm establishes connection with meter through IrDA and sends the data (Figure 38). The connection stops automatically once the data is transferred.
10. You can save the transferred data to a text file. See 'Saving data' section in page 35.




Figure 37 : Selecting options for printing memory locations




Figure 38 : Transfer Stored data to CyberComm

3. Calibration Mode

3.1 About Calibration

PCD 650 series meters are factory calibrated and allows you to measure pH/mV/ion/conductivity/resistivity/TDS/salinity/DO(%)/DO(mg/L). Calibrate to all measurement ranges to ensure the highest accuracy throughout all measurement range. However, it is recommended that, for higher accuracy, you calibrate your meter before you make measurements for the first time.

Calibration should be carried out each time a new electrode is attached to the meter or when you suspect that the meter/electrode is out of calibration.

3.1.1 About Temperature Calibration

It is important to ensure that temperature calibration is carried out prior to pH, conductivity and DO calibration since temperature readings affect the accuracy of pH, conductivity and DO measurements. You need to perform temperature calibration only if the temperature value displayed on the meter is different from that of a calibrated thermometer or if cell constant setting is changed. A temperature offset calibration of $\pm 5\text{ }^{\circ}\text{C}/\pm 9\text{ }^{\circ}\text{F}$ from the default reading is allowed for ATC mode.

3.1.2 About pH Calibration

When you re-calibrate your meter, previous pH calibration points are replaced on a point by point basis. For example, if you previously calibrated your meter at pH 4.01, 7.00, and 10.01, and you have now re-calibrated at pH 7.00, the meter retains the old calibration data at pH 4.01 and pH 10.01. The meter shows previously calibrated points in the display when the meter is in pH measurement mode. To completely re-calibrate the meter, or when you use a replacement probe, it is best to clear the previous calibration and re-calibrate the meter at all points. Refer page 46 for information on how to clear previous pH calibration.

The meter supports four internationally recognized standard buffer groups: USA, NIST, DIN & PWB. The default buffer group is USA. Refer page 82 for information on how to set the meter to a particular buffer group

The meter is capable of calibrating up to 6 points, depending on the standard buffer selected. When completely re-calibrating the meter, the first point of calibration should be one of the following, depending on your choice of standard buffer group.

Buffer Group	First Point of Calibration (when complete re-calibration)	Other Available Calibration Points
USA	pH 7.00	pH 1.68, 4.01, 10.01, and 12.45
NIST	pH 6.86	pH 4.01, 6.86, 9.18, and 12.45
DIN	pH 6.79	pH 1.09, 3.06, 4.65, 9.23, and 12.75
PWB	pH 6.97	pH 4.10

Table 2: Buffer Groups and Calibration Points

The meter automatically recognizes and calibrates to these standard pH buffer values, which makes pH calibration faster and easier.

3.1.3 About Ion Calibration

The meter supports Ion calibration up to 8 points with minimum of 2-points. The available 8-points are 0.001, 0.01, 0.1, 1, 10, 100, 1000 & 10000.

The meter guides you through the calibration process with on-screen instructions and hints. If the second point and subsequent points are not within the allowable calibration window (15mV/decade to 90mV/decade), the meter does not accept the calibration.

When you try to re-calibrate the meter with ISE, the meter gives you 2 options:

- **Clear the previous calibration** (choose this if you wish to delete all previously calibrated points and re-calibrate with a new type of Ion)
- **Retain the previous calibration** (choose this if you wish to retain previously calibrated points and re-calibrate new points or overwrite existing points with same type of Ion).

3.1.4 About Conductivity/Resistivity/TDS/Salinity Calibration

Before measuring conductivity, resistivity, TDS or salinity, you will need to calibrate the meter with known conductivity, resistivity, TDS or salinity values.

This meter is capable of performing either automatic or manual calibration.

In the automatic calibration mode, the meter automatically detects and verifies the appropriate known calibration standards solutions being calibrated before accepting these particular calibration standards as one of its calibration values in a specific measurement range. This automatic calibration mode frees you from cumbersome calibration procedure.

This meter can perform a single- or multi-point calibration. You will need to set your meter to single- or multi-point calibration in the Setup mode for conductivity, resistivity, TDS or salinity.

Refer to the setup section for the particular mode you will be measuring. Instead of calibrating for TDS directly using TDS calibration standard solutions, you can have TDS calibration by using the conductivity calibration method and enter the appropriate TDS conversion factor into the meter.

For more information regarding TDS Conversion Factor determination, please refer to page 106.

3.1.5 About DO(%) and DO (mg/L) Calibration

The calibration of % Saturation of DO will linearly affect the measurement for DO in mg/L. The amount of oxygen dissolved in water will depend on its temperature, atmospheric pressure and its salinity. It is therefore very important that the temperature is calibrated if necessary prior to the DO calibration.

Hence calibration in % Saturation of DO should be carried out first. This is described in the following section.

3.1.6 Prepare the Meter for Calibration

Before starting calibration, make sure the meter is in the appropriate measurement mode.

For pH

Connect the pH probe to the BNC connector of the meter.

Be sure to remove the protective electrode storage bottle or rubber cap of the electrode before calibration or measurement. If the electrode has been stored dry, wet the electrode in clean water for 10 minutes before calibrating or taking readings to saturate the pH electrode surface and minimize drift.

Wash your electrode in clean water after use, and store in electrode storage solution. If storage solution is not available, use pH 4.01 or 7.00 buffer solution. Do not reuse buffer solutions after calibration. Contaminants in the solution can affect the calibration, and eventually the accuracy of the measurements.

It is recommended that you perform at least a 2-Point Calibration using standard buffers that adequately cover the expected measurement range, prior to measurement.

For Ion

Connect the ISE to the BNC connector of the meter.

Remove plastic protective cap of ISE. Briefly rinse the electrode with clean clean water to remove any residues. Rinse ISE before and after each calibration or sample measurement to avoid cross-contamination. Ensure that you use new or fresh standard solutions during calibration. Do not reuse Ion standard solution as it may be contaminated and affect the calibration and accuracy of measurements.

For Conductivity

Connect the conductivity probe with built-in temperature sensor into the 8-pin connector of the meter.

For best results, select a standard value close to the sample value you are measuring. Alternatively use a calibration solution value that is approximately 2/3 the full-scale value of the measurement range you plan to use. For example, in the 0 to 2000 μS conductivity range, use a 1413 μS solution for calibration.

Perform calibration for all measurement ranges to ensure the highest accuracy throughout all measurement range. Calibration for different ranges is indicated in the Technical Specifications table on page 5, calibration factors are applied only to their respective ranges

If you are measuring in solutions with Conductivity lower than 100 $\mu\text{S}/\text{cm}$ or TDS lower than 50 ppm, calibrate the meter at least once a week to get good accuracy. If you are measuring in the mid ranges and you wash the electrode in de-ionized water and store it dry, calibrate the meter once a month. If you take measurements at extreme temperatures, calibrate at least once a week.

Ensure that you use new conductivity standard solutions or sachets during calibration. Do not reuse standard solutions as it may be contaminated and affect the calibration and accuracy of measurements. Use fresh calibration solution each time you calibrate your meter. Keep solutions in a dry and cool environment if possible.

For DO(%) and DO (mg/L) Calibration

Before starting calibration, make sure you are in the correct measurement mode and in the correct calibration sequence. **The temperature and the % Saturation calibration must be done first before attempting to do the mg/L (ppm) Concentration calibration.**

Rinse the probe well in the de-ionized (DI) water or rinse solution and wipe the probe carefully taking care of the membrane.

Calibrate the meter in all the modes to ensure the highest accuracy throughout the DO measurement range. In % Saturation, the meter is able to perform either a one point calibration or a 2 point calibration. For one point calibration, it is recommended that you perform a 100% Saturation calibration in saturated air. If you opt for 2 point calibration, you can calibrate for 100% Saturation in saturated air and 0% Saturation using a zero oxygen solution.

All new calibration values will automatically override the existing data. It is recommended to calibrate the meter periodically and or if it is suspected to be inaccurate.

Always rinse the probe with either DI water or rinse solution before and after each calibration/sample measurement. When calibrating in air, make sure that any water droplets from the probe's membrane are removed.

3.1.7 Accessing Calibration mode

From measurement mode, press **CAL (F2)** key. The meter goes to corresponding calibration mode, based on the selected measurement mode. If the meter is password protected, you will be prompted to enter password. (Refer the below section)

3.1.8 Accessing Calibration mode when password protection enabled

Follow the steps below to access the calibration mode, when password protection is enabled (Refer page 80).

1. Make sure you are in measurement mode. If required, press **MODE (F3)** to switch to the measurement mode for which you wish to perform calibration.
2. Press **CAL (F2)** to go to calibration mode. Login Password screen appears (Figure 39). The meter expects the 5-digit password specified in system setup. (Refer 'System Settings – Page 5' in page 80)



Figure 39 : Login password screen

Note: You can enter '00000' (read-only password) if you wish to view the calibration report of the last calibration. You are not allowed to perform calibration when you enter 'read-only password'.

3. Press up ▲ & down ▼ arrow keys to enter the first digit of the password and then press **NEXT (F3)** key to move to the next digit.
4. The next digit is selected. Press up ▲ & down ▼ arrow keys to enter the second digit of the password.
5. Similarly enter all 5-digits.
6. Press **ENTER** key to confirm the password.
7. When the correct password is entered, the 'Calibration – Rinse Electrode' screen appears (Refer Figure 48-(a)).

Note: If you enter an incorrect password, the screen shows 'Try again'. If an incorrect password is entered for 3 consecutive times, the meter goes to measurement mode.

3.2 Temperature Calibration

The built-in temperature sensor of conductivity and DO probe included with the meter are factory calibrated. **The built-in ATC probe of the conductivity cells can be used for temperature readout and compensation of the pH values.** DO in mg/L is dependent on temperature, so it is first necessary to calibrate or verify the temperature reading. Calibrate the probes only if you suspect temperature errors may have occurred over a long period of time or if you have a replacement probe. This procedure offers offset adjustment of probe to ensure more accurate temperature measurement.

Use a thermometer which is known to be accurate to measure the temperature of your sample.

3.2.1 Temperature Calibration for ATC mode

Make sure you have selected 'ATC' and required unit of measurement (°C or °F) in Temperature settings. Refer 'Temperature Setup' section in page 98 for more details.

1. Switch on the meter. Make sure the meter is in measurement mode.
2. Press **CAL (F2)** to go to calibration mode.

Note: If the meter is password protected, you will be prompted to enter a password. Refer 'Accessing Calibration mode when password protection enabled' in page 42.

3. The meter shows 'Calibration-Rinse Electrode' screen [Figure 48-(a)] for few seconds and then shows the cell constant adjustment screen.
4. Press **NEXT (F3)** key.
5. Press **TEMP (F1)** to go to temperature calibration. The temperature calibration screen appears (Figure 40).






Figure 40: Temperature calibration screen

6. The screen shows two readings. The upper display shows the temperature reading of the solution with respect to previous calibration (if any) & lower displays shows the temperature reading of the solution without any calibration (default reading). Use  &  keys to adjust the upper display to the temperature reading of the thermometer.

Note: The meter allows you to adjust the upper display reading up to ± 5 °C or ± 9 °F. (Calibration window)



7. Press **ENTER** key to confirm temperature value.

3.2.2 Temperature Calibration for MTC mode

Make sure you have selected 'MTC' and required unit of measurement (°C or °F) in Temperature settings. Refer 'Temperature Setup' section in page 98 for more details.

1. Switch on the meter. Make sure the meter is in measurement mode.
2. Press **CAL (F2)** to go to calibration mode.





Note: If the meter is password protected, you will be prompted to enter a password. Refer 'Accessing Calibration mode when password protection enabled' in page 42.

3. The meter shows 'Calibration-Rinse Electrode' screen [Figure 48-(a)] for few seconds and then shows the cell constant adjustment screen.
4. Press **NEXT (F3)** key.
5. Press **TEMP (F1)** to go to temperature calibration. The temperature calibration screen appears.
6. The screen shows two readings. The upper display shows the temperature reading of the solution with respect to previous calibration (if any) & lower displays shows the temperature reading of the solution without any calibration (default reading). Use  &  keys to adjust the upper display to the temperature reading of the thermometer.

Note: The meter allows you to adjust the upper display reading to any value within the measuring range -10.0 °C to 110.0 °C (14.0 °F to 230.0 °F).

7. Press **ENTER** key to confirm temperature value.

Function Keys available in temperature calibration screen:

NEXT (F3)	Goes to measurement mode from where you entered calibration
ESC (F4)	Goes to measurement mode from where you entered calibration
ENTER	Confirms calibration
 	Increase/decrease temperature reading
 	(Not functional)

3.3 pH Calibration

3.3.1 pH Calibration with a Standard Buffer


Make sure you have selected a standard buffer with which you intend to perform pH calibration. Refer 'pH Setup' section in page 82 for more details of setting buffer types.

To start pH Calibration:

1. Switch on the meter and make sure the meter is in pH measurement mode.
2. Press **CAL (F2)** to start calibration.

Note: If the meter is password protected, you will be prompted to enter a password. Refer 'Accessing Calibration mode when password protection enabled' in page 42.

3. The meter shows 'Calibration-Rinse Electrode' screen [Figure 41 (a)] for few seconds and then shows the pH calibration screen [Figure 41-(b)].



(a) (b)
Figure 41: pH Calibration Screens

4. Rinse the electrode in clean water and prepare electrode for calibration. Refer 'Prepare the meter for measurement' section in page 40.

Note: If you wish to completely re-calibrate the meter, you need to clear previous calibration data. Press **CLR-C (F2)** key to clear previous calibration. The meter shows you confirmation screen. Press **ENTER** key to confirm deleting previous calibration. Once cleared, you need to calibrate the first point that corresponds to your selected buffer group, as mentioned on page 39.

5. Dip the probe in calibration buffer. The tip of the probe must be completely immersed into the solution. Stir the probe gently to create a homogeneous solution.
6. The display shows the pH reading. The meter scans through all the available (un-calibrated) points for the selected buffer group until it finds a close match within its acceptable calibration window. (Refer Specification section in page 99 for calibration window values). Once found a match, the display shows 'Stable' indicator.
7. Press **ENTER** key to confirm the calibration.
8. Rinse the probe with clean water.
9. Place it in the next buffer and follow the steps 5 and 7 to calibrate other points.

Function Keys available in pH Calibration mode:

TEMP (F1)	Goes to temperature calibration
CLR-C (F2)	Clears previous calibration (if any) after ENTER key is pressed in confirmation screen
NEXT (F3)	Shows calibration report
ESC (F4)	Exits from calibration and goes back to pH measurement mode
ENTER	Confirms the calibration
▲ ▼ ◀ ▶	(Not functional)

3.3.2 pH Calibration with a User-defined Buffer

If you selected 'USER' (Custom) buffer in the pH Setup, the following screen is shown when you enter calibration mode. You need to prepare at least 2 custom buffers of known pH values.

Note: Custom buffer solution values should be at least **1 pH** unit apart from each other. Otherwise, the meter will not accept the buffer values.










Figure 42: Calibration screen for user-defined buffer

1. Rinse the electrode in clean water and prepare electrode for calibration.

Note: If you wish to completely re-calibrate the meter, you need to clear previous calibration data. Press **CLR-C (F2)** key to clear previous calibration. The meter shows you confirmation screen. Press **ENTER** key to confirm deleting previous calibration.

2. Dip the probe in custom calibration buffer. The tip of the probe must be completely immersed into the solution. Stir the probe gently to create a homogeneous solution.
3. The screen shows 2 readings. The upper display shows the pH reading of the solution with respect to previous calibration (if any) & lower display shows the pH reading of the solution without any calibration. Use  &  keys to adjust the upper display to the pH value of your custom buffer.
4. Press **ENTER** key to confirm the calibration.
5. Rinse the probe with clean water. Place it in the next buffer and follow the steps 2, 3 and 4 to calibrate other points.



Function Keys available in pH Calibration mode:

TEMP (F1)	Goes to temperature calibration
CLR-C (F2)	Clears previous calibration (if any) after ENTER key is pressed for the confirmation screen
NEXT (F3)	Shows calibration report
ESC (F4)	Exits from calibration and goes back to pH measurement mode
ENTER	Confirms the calibration
 	Increases/decreases pH buffer reading
 	(Not functional)

3.3.3 Calibration Report

Calibration report gives you detailed information on calibration. It includes date & time, buffer group, offset, temperature, number of days calibration is over due and slope information.

To View calibration Report:

1. From pH measurement mode, press left  or right  arrow key to navigate to other available functions until you see **REPO** function in the LCD.
2. Press **REPO (F2)** key. The first page of calibration report is shown in the display.
3. Press **PAGE (F1)** to view the second page of the report.
4. Press **PRIN (F2)** to transfer the calibration report to computer through IrDA. (Refer page 37 to print data).




Figure 43: pH Calibration Report

Example: In the given pH calibration report (Refer Figure 43), 4-point calibration has been done for USA buffer group (pH 1.68, pH 4.01, pH 7.00 & pH 12.45).

- The slope is 93 for the range enveloped from pH 1.68 to pH 4.01.
- The slope is 88 for the range enveloped from pH 4.01 to pH 7.00.
- The slope is 94 for the range enveloped from pH 7.00 to pH 12.45 where pH 10.01 calibration point has been skipped.

Function Keys available in pH calibration report screen:

PAGE (F1)	Goes to the second page of the calibration report
BACK (F1)	Goes to the first page of the calibration report
PRIN (F2)	Transfers calibration report to Computer through IrDA
NEXT (F3)	Goes to pH measurement mode
ESC (F4)	Goes to pH measurement mode
ENTER	(Not functional)
▲ ▼ ◀ ▶	(Not functional)

3.3.4 Average Slope Indicator of pH Probe

Each time you perform pH calibration; the meter calculates the average slope of your probe and graphically indicates it in the header section of the LCD screen.




Figure 44 : Average slope indicator

Number of bars in the indicator shows the slope value:

Number of Bars	Average Slope of the pH Probe
4	Above 90%
3	90% to 80%
2	80% to 70%
1	Below 70%


3.4 mV Calibration

Use a standard ORP solution of known value for calibration. You need to calibrate only 1-point.

1. Switch on the meter. Make sure the meter is in mV measurement mode.
2. Press **CAL (F2)** to go to calibration mode.

Note: If the meter is password protected, you will be prompted to enter a password. Refer 'Accessing Calibration mode when password protection enabled' in page 42.

3. The meter shows 'Calibration-Rinse Electrode' screen [Figure 41 (a)] few seconds and then shows the mV calibration screen [Figure 45 (a)].



(a) (b)
Figure 45 : mV calibration screen & calibration report

4. The screen shows two readings. The upper display shows the mV reading of the solution with respect to previous calibration (if any) & lower displays shows the absolute mV reading of the solution without any calibration (default reading). Use ▲ & ▼ keys to adjust the upper display to the mV value of the solution.

Note: The meter allows you to adjust the upper display reading up to ± 150 mV with respect to the default reading.

5. Press **ENTER** key to confirm the entered value.
6. The calibration is completed. The meter shows the calibration report [(Figure 45-(b))].
7. Press **ESC (F4)** to go to measurement mode. The meter shows the relative mV reading of the solution in measurement mode, if offset is not zero.

Note: The function of the keys available on the mV calibration/ report screen is same as previously described in pH calibration with a user-defined buffer section (page 48).

3.4.1 mV Calibration Report

Calibration report gives you information on calibration. It includes date & time on which the last calibration was done and the offset.

To View calibration Report:

1. From mV measurement mode, press left ◀ or right ▶ arrow key to navigate to other available functions until you see **REPO** function in the LCD
2. Press **REPO (F2)** key. The calibration report is shown in the display [(Figure 45 (b))].
3. Press **PRIN (F2)** to transfer the calibration report to the computer.(Refer page 37 to print data)

3.5 Ion Calibration

Use standard solutions of 0.001, 0.01, 0.1, 1, 10, 100, 1000 & 10000 ppm for calibration. You need to calibrate minimum of 2-points. Follow the instruction in 'Prepare the meter for measurement' section in page 40.

1. Switch on the meter. Make sure the meter is in Ion measurement mode.
2. Press **CAL (F2)** to go to calibration mode.

Note: If the meter is password protected, you will be prompted to enter a password. Refer 'Accessing Calibration mode when password protection enabled' in page 42.

3. The meter shows 'Calibration-Rinse Electrode' screen [Figure 41-(a)] few seconds and then shows the Ion calibration screen [Figure 46-(b)]




Figure 46 : Ion calibration screens

Note: If there is an existing ion calibration in the meter, you will be given two options. [Figure 46-(a)]

- **Clear the previous calibration (CLR-C)** – choose this if you wish to delete all previously calibrated points and re-calibrate with a new type of ion.
- **Retain the previous calibration (NEXT)** – choose this if you wish to retain previously calibrated points and re-calibrate new points (or overwrite existing points) with same type of ion.

4. Dip the ISE in calibration solution. The tip of the probe must be completely immersed into the solution. Stir the probe gently to create a homogeneous solution.
5. The calibration screen displays two readings. The upper display shows the lowest calibration point 0.001 ppm. The lower display shows the absolute mV reading of the solution without any calibration (default reading). Use ▲ & ▼ keys to select the required calibration point in the upper display.

6. Allow time for the reading to stabilize. Press **ENTER** key to confirm the selected point. The meter flashes the upper display to acknowledge the first point calibration.
7. The upper display shows the next calibration point.
8. Rinse the ISE with clean water. Place it in the next calibration solution and follow the steps 4 through 6 to calibrate other points.


Note: The meter accepts the second and subsequent points only if the mV readings are within the calibration window (**15mV/decade to 90mV/decade**).

9. Press **ESC (F4)** to go to measurement mode.

Note: The function of the keys available on the Ion calibration/ report screen is same as previously described in pH calibration with a user-defined buffer section (page 48).

3.5.1 Calibration Report

Calibration report gives you detailed information on calibration. It includes date & time, calibration points (Ion concentrations), absolute mV reading for each point and slope.





IrDA D>> Report Ion		
04 - Jan - 06 / 16:40		
Concen	mV	Slope mV
0.001	---	---
0.01	0.0	56
0.1	56.0	---
1	---	50
10	156.0	---
100	---	---
1000	---	---
10000	---	---

PRIN NEXT ESC

Figure 47 : Ion calibration report

Example: In the given Ion calibration report (Refer Figure 47), calibration has been done for 0.01, 0.1 & 10 Ion concentrations. The corresponding absolute mV readings are 0.0mV, 56.0mV & 156mV. The slope is 56 mV/decade for the range enveloped from 0.01 to 0.1 ppm. Similarly, the slope is 50 for the range enveloped from 0.1 to 10ppm where 0.1 calibration point has been skipped.

To View calibration Report:

1. From mV measurement mode, press left  or right  arrow key to navigate to other available functions until you see **REPO** function in the LCD
2. Press **REPO (F2)** key. The calibration report is shown in the display.
3. Press **PRIN (F2)** to transfer the calibration report to computer through IrDA.

3.6 Conductivity Calibration

3.6.1 Manual Calibration

Make sure you have selected a standard solution with which you intend to perform conductivity calibration, refer page 86 for more details of setting solution types.

To start manual Calibration for conductivity:

Following is the procedure for **single point calibration**:

1. Switch on the meter and make sure the meter is in conductivity measurement mode.
2. Dip the probe into the calibration standard. Immerse the probe tip beyond the upper steel band. Stir the probe gently to create a homogeneous sample. Allow time for the reading to stabilize.
3. Press **CAL (F2)** to start calibration.

Note: If the meter is password protected, you will be prompted to enter a password. Refer 'Accessing Calibration mode when password protection enabled' in page 42.

4. The meter shows 'Calibration-Rinse Electrode' screen [Figure 48 (a)] for few seconds to prompt user to rinse electrode with de-ionized water before calibration (Refer 'Prepare the meter for measurement' section in page 40).




Figure 48 : Calibration Screens

5. The meter then shows cell constant adjustment screen [Figure 48-(b)]. The upper display shows the cell constant of the conductivity cell & lower display shows the measured value of the solution with adjusted cell constant with respect to default calibration. Press **▲** & **▼** keys to adjust the cell constant for your custom solution in upper display.
6. Press **ENTER** key to confirm the calibration.

Note: If you wish to completely re-calibrate the meter, you need to clear previous calibration data. Press **CLR-C (F2)** key to clear previous calibration. The meter shows you confirmation screen. Press **ENTER** key to confirm deleting previous calibration.




Figure 49 : Conductivity calibration Screen

7. The upper display shows the conductivity reading of the solution with respect to previous calibration (if any) & lower display shows the conductivity reading of the solution without any calibration. Use ▲ & ▼ keys to adjust the upper display of the conductivity value of your custom solution.
8. Press **ENTER** key to confirm the calibration.
9. Press **ESC (F4)** to go to measurement mode.
10. As for the case of **multi point calibration**, rinse the probe with de-ionized water, and repeat step 1 to 7 for every calibration using the desired calibration solutions until all points have been calibrated.

Function Keys available in Conductivity Calibration mode:

TEMP (F1)	Goes to temperature calibration
CLR-C (F2)	Clears previous calibration (if any) after ENTER key is pressed in confirmation screen
NEXT (F3)	Shows calibration report
ESC (F4)	Exits from calibration and goes back to conductivity measurement mode
ENTER	Confirms the calibration
▲ ▼	Increases/decreases conductivity cell reading
◀ ▶	(Not functional)

3.6.2 Automatic calibration (For Conductivity Calibration)

In the Automatic Calibration mode, the meter is capable of accepting either single-point or up to 5 points for multi-point calibration with maximum of 1 point per specific measurement range. Select automatic calibration mode in the Conductivity Setup screen. See 'Conductivity Settings – Page 1' on page 86 for the set up procedure. Press **(F2)** to start calibration and the meter displays cell adjustment screen as mentioned in the above section.

The following screen is displayed after cell adjustment screen, if you have selected '**Auto**' in Calibration mode and '**MULTI**' in Calibration Point:




Figure 50 : Conductivity calibration Screen-Auto

1. Rinse the electrode in de-ionized water and prepare electrode for calibration. Refer 'Prepare the meter for measurement' section in page 40.

Note: If you wish to completely re-calibrate the meter, you need to clear previous calibration data. Press **CLR-C (F2)** key to clear previous calibration. The meter shows you confirmation screen. Press **ENTER** key to confirm deleting previous calibration.

2. Dip the probe into the calibration standard. Immerse the probe tip beyond the upper steel band. Stir the probe gently to create a homogeneous sample. Allow time for the reading to stabilize.
3. Press **CAL (F2)** to go to calibration mode. The screen shows conductivity reading. The meter scans through all the available points for the selected solution group until it finds a close match within its acceptable calibration window. Once found a match, the display shows 'Stable' indicator.
4. Press **ENTER** key to confirm the calibration.
5. Rinse the probe with de-ionized water. Place it in the next solution and follow the steps 2, 3 and 4 to calibrate other points.

Function Keys available in Conductivity Calibration mode:

TEMP (F1)	Goes to temperature calibration
CLR-C (F2)	Clears previous calibration (if any) after ENTER key is pressed for the confirmation screen
NEXT (F3)	Shows calibration report
ESC (F4)	Exits from calibration and goes back to conductivity measurement mode
ENTER	Confirms the calibration
▲▼ ◀▶	Not functional

6. Press **ESC (F4)** to go to measurement mode.

Note: If the user has selected '**SINGLE**' point calibration and '**AUTO**' calibration mode, the meter will go to measurement mode after step 4.

3.6.3 Calibration Report

Calibration report gives you detailed information on calibration. It includes date & time, calibration points, range, factor and cell constant.

To View calibration Report:

1. From conductivity measurement mode, press left ◀ or right ▶ arrow key to navigate to other available functions until you see **REPO** function in the LCD.
2. Press **REPO (F2)** key. The calibration report is shown in the display.
3. Press **PRIN (F2)** to transfer the calibration report to computer through IrDA. (Refer page 37 to print data).

Cal. point	Range	Cal. fact
---	1	0.9900
84.000 μ S	2	0.9900
1.413 mS	3	0.9912
12.880 mS	4	0.9895
111.800 mS	5	0.9902

PRIN NEXT ESC

Figure 51: Conductivity Calibration Report

Function Keys available in conductivity calibration report screen:

PRIN (F2)	Transfers calibration report to Computer through IrDA
NEXT (F3)	Goes to conductivity measurement mode
ESC (F4)	Goes to conductivity measurement mode
ENTER	(Not functional)
◀ ▶ ◀ ▶	(Not functional)

Note: Auto calibration can also be done for electrode with cell constant 0.4 – 2.

3.7 Resistivity Calibration

Use a standard solution of known value for calibration. Use the single-point standardization option to measure samples that close in value and multi-point standardization to measure wide range of samples.

1. Switch on the meter. Make sure the meter is in resistivity measurement mode.
2. Press **CAL (F2)** to go to calibration mode.
3. The meter shows 'Calibration-Rinse Electrode' screen [Figure 48-(a)] few seconds and then shows the cell constant adjustment screen [Figure 52-(a)].

Note: If the meter is password protected, you will be prompted to enter a password. Refer 'Accessing Calibration mode when password protection enabled' in page 42.




Figure 52 : Resistivity Cell constant & resistivity calibration

4. The upper display of the resistivity cell constant screen [Figure 52-(a)] shows the resistivity cell constant of your solution & lower display shows the measured value of the solution with adjusted cell constant. Press ▲ & ▼ keys to adjust the cell constant for your custom solution in upper display.
5. Press **ENTER** key to confirm the entered value and to go to resistivity calibration screen.
6. The screen shows two readings. The upper display shows the resistivity reading of the solution with respect to previous calibration (if any) & lower display shows the resistivity reading of the solution without any calibration. Use ▲ & ▼ keys to adjust the upper display of the resistivity value of your custom solution.
7. Press **ENTER** key to confirm the entered value.

Note: The function of the keys available on the resistivity cell constant/calibration/ report screen is same as previously described in conductivity calibration.


8. Rinse the probe with de-ionized water. Place it in the next solution and follow the steps 2 to 7 to calibrate other points, if '**MULTI**' point calibration is selected.
9. Press **ESC (F4)** to go to measurement mode. The meter shows the resistivity reading of the solution in measurement mode.

3.7.1 Resistivity Calibration Report

Calibration report gives you information on calibration. It includes date & time on which the last calibration was done and the offset.

To View resistivity Report:

1. From resistivity measurement mode, press left ◀ or right ▶ arrow key to navigate to other available functions until you see **REPO** function in the LCD
2. Press **REPO (F2)** key. The calibration report is shown in the display [Figure 53].
3. Press **PRIN (F2)** to transfer the calibration report to the computer.(Refer page 37 to print data)



IrDA Report Res		
04 - Jan - 06 / 16:40		
Cell const: 1.000		
Value	Range	Cell 'k'
1.000 kΩ	1	1.255
	2	1.255
	3	1.255
	4	1.255
	5	1.255
<div> <div></div> <div>PRINT</div> <div>NEXT</div> <div>ESC</div> </div>		

Figure 53 : Resistivity report screen

3.8 Salinity Calibration

Use a standard solution of known value for calibration. Use the single-point standardization option to measure samples that close in value and multi-point standardization to measure wide range of samples.

1. Switch on the meter. Make sure the meter is in salinity measurement mode.
2. Press **CAL (F2)** to go to calibration mode.

Note: If the meter is password protected, you will be prompted to enter a password. Refer 'Accessing Calibration mode when password protection enabled' in page 42.

3. The meter shows 'Calibration-Rinse Electrode' screen [Figure 48-(a)] few seconds and then shows the cell constant adjustment screen [Figure 54-(a)].




Figure 54 : Salinity Cell constant & salinity calibration

4. The upper display of the cell constant adjustment screen [Figure 54-(a)] shows the salinity cell constant of your solution & lower display shows the measured value of the solution with adjusted cell constant. Press ▲ & ▼ keys to adjust the cell constant for your custom solution in upper display.
5. Press **ENTER** key to confirm the entered value and to go to salinity calibration screen.
6. The screen shows two readings [Figure 54-(b)]. The upper display shows the salinity reading of the solution with respect to previous calibration (if any) & lower display shows the salinity reading of the solution without any calibration. Use ▲ & ▼ keys to adjust the upper display of the salinity value of your custom solution.
7. Press **ENTER** key to confirm the entered value.



Note: The function of the keys available on the salinity cell constant/calibration/ report screen is same as previously described in conductivity calibration.


8. Rinse the probe with de-ionized water. Place it in the next solution and follow the steps 2 to 7 to calibrate other points, if '**MULTI**' point calibration is selected.
9. Press **ESC (F4)** to go to measurement mode. The meter shows the salinity reading of the solution in measurement mode.

3.8.1 Salinity Calibration Report

Calibration report gives you information on calibration. It includes date & time on which the last calibration was done and the offset.

To View salinity Report:

1. From salinity measurement mode, press left  or right  arrow key to navigate to other available functions until you see **REPO** function in the LCD
2. Press **REPO (F2)** key. The calibration report is shown in the display [Figure 55].
3. Press **PRIN (F2)** to transfer the calibration report to the computer.(Refer page 37 to print data)



Value	Range	Cell 'k'
1.000 PPt	1	1.255
	2	1.255
	3	1.255
	4	1.255
	5	1.255

Navigation buttons: **PRINT** **NEXT** **ESC**

Figure 55 : Salinity report screen


3.9 TDS Calibration

You can commence calibration in the TDS mode by using the conductivity calibration method and after setting the correct TDS factor. For more information regarding TDS conversion factor determination, please refer to page 106. For the rest of the calibration process, follow steps as mentioned in the section of manual calibration on page 55. Use a standard solution of known value for calibration. Use the single-point standardization option to measure samples that close in value and multi-point standardization to measure wide range of samples.


1. Switch on the meter. Make sure the meter is in TDS measurement mode.
2. Press **CAL (F2)** to go to calibration mode.

Note: If the meter is password protected, you will be prompted to enter a password. Refer 'Accessing Calibration mode when password protection enabled' in page 42.

3. The meter shows 'Calibration-Rinse Electrode' screen [Figure 48-(a)] few seconds and then shows the cell constant adjustment screen for TDS [Figure 56(a)].



(a)



(b)

Figure 56 : TDS Cell constant adjustment & TDS calibration screen

4. The upper display of the TDS cell constant screen [Figure 56-(a)] shows the TDS cell constant of your solution & lower display shows the measured value of the solution with adjusted cell constant. Press ▲ & ▼ keys to adjust the cell constant for your custom solution in upper display.
5. Press **ENTER** key to confirm the entered value and to go to TDS calibration screen.
6. The screen shows two readings [Figure 56-(b)]. The upper display shows the TDS reading of the solution with respect to previous calibration (if any) & lower display shows the TDS reading of the solution without any calibration. Use ▲ & ▼ keys to adjust the upper display of the TDS value of your custom solution.
7. Press **ENTER** key to confirm the entered value.

Note: The function of the keys available on the TDS cell constant/calibration/ report screen is same as previously described in conductivity calibration.

8. Rinse the probe with de-ionized water. Place it in the next solution and follow the steps 2 to 7 to calibrate other points, if 'MULTI' point calibration is selected.
9. Press **ESC (F4)** to go to measurement mode. The meter shows the TDS reading of the solution in measurement mode.

3.9.1 TDS Calibration Report

Calibration report gives you information on calibration. It includes date & time on which the last calibration was done and the offset.

To View TDS Report:

1. From TDS measurement mode, press left ◀ or right ▶ arrow key to navigate to other available functions until you see **REPO** function in the LCD.
2. Press **REPO (F2)** key to go to calibration report screen (Figure 57).
3. Press **PRIN (F2)** to transfer the calibration report to the computer. (Refer page 37 to print data).

Value	Range	Cell 'k'
1.000 PPt	1	1.255
	2	1.255
	3	1.255
	4	1.255
	5	1.255

PRINT NEXT ESC

Figure 57 : TDS report screen

3.10 DO Calibration in % Saturation Mode (with ATC)

The PCD 650 can be calibrated quickly and easily in air. In % Saturation, the meter is able to perform either a one point calibration or a 2 point calibration. For one point calibration, it is recommended that you perform a 100% Saturation calibration in saturated air. If you opt for 2 point calibration, you can calibrate for 100% Saturation in saturated air and 0% Saturation using a zero oxygen solution.

The PCD 650 meter is capable of measuring barometric pressure with its built-in pressure sensor. In the event, the pressure reading is inaccurate, you can calibrate the value from the setup menu. For setting barometric pressure range, please refer page 86.

3.10.1 To calibrate 100% saturation

1. Switch on the meter and make sure the meter is in % saturation mode.
2. Hold the probe in the air gently with the sensor facing down and press **CAL (F2)** to start calibration.

Note: If the meter is password protected, you will be prompted to enter a password. Refer 'Accessing Calibration mode when password protection enabled' in page 42.

3. The meter shows 'Dissolved O₂ Calibration-Rinse Electrode' screen [Figure 48-(a)] for few seconds to prompt user to rinse electrode with de-ionized water before calibration




Figure 58: Saturation Calibration Screens

4. Rinse the probe well with de-ionized water. For best result, blot the end of the probe dry. Do not touch the membrane.
5. The meter then shows saturation calibration screen [Figure 58-(b)]. The primary display will show the current value of measurement. Wait for the reading to stabilize.

6. Press **ENTER** key to confirm the calibration. The meter automatically calibrates to 100% air saturation and returns to the measurement mode.

Note: If you wish to completely re-calibrate the meter, you need to clear previous calibration data. Press **CLR-C (F2)** key to clear previous calibration. The meter shows you confirmation screen. Press **ENTER** key to confirm deleting previous calibration.




Figure 59 : Saturation measurement Screen

Function Keys available in saturation calibration mode:

TEMP (F1)	Goes to temperature calibration
CLR-C (F2)	Clears previous calibration (if any) after ENTER key is pressed in confirmation screen
NEXT (F3)	Shows calibration report
ESC (F4)	Exits from calibration and goes back to saturation measurement mode
ENTER	Confirms the calibration
▲ ▼ ◀ ▶	(Not functional)

3.10.2 To calibrate 0% saturation




Figure 60 : 0% saturation calibration Screen

1. Press **MODE** key to select % Saturation mode.
2. Immerse the DO probe in 0% solution. Stir gently to create a homogenous solution.
3. Press **CAL** key to calibrate the meter. The meter shows 'Dissolved O₂ Calibration-Rinse Electrode' screen [Figure 48(a)] for few seconds to prompt user to rinse electrode with de-ionized water before calibration.
4. The meter then shows saturation calibration screen [Figure 60].
5. Wait for the reading to stabilize.
6. The primary display will show the current value of measurement.
7. Press **ENTER** key to confirm the calibration. The meter automatically calibrates to 0% saturation and returns to the measurement mode [Figure 59].



Note: If you wish to completely re-calibrate the meter, you need to clear previous calibration data. Press **CLR-C (F2)** key to clear previous calibration. The meter shows you confirmation screen. Press **ENTER** key to confirm deleting previous calibration. It will **clear all the calibration data including mg/L data**.

Note: The keys that appear in 0% saturation calibration mode functions similar to the one as described in 100% saturation mode. (Refer page 66)

3.10.3 % DO Calibration Report

Calibration report gives you detailed information for the % saturation. It includes date & time, 0% and 100% saturation mV value, % saturation offset calibration and barometric pressure at which the solution was measured.

To View calibration Report:

1. From % saturation measurement mode, press left  or right  arrow key to navigate to other available functions until you see **REPO** function in the LCD.
2. Press **REPO (F2)** key. The calibration report is shown in the display.
3. Press **PRIN (F2)** to transfer the calibration report to computer through IrDA. (Refer page 37 to print data).








Figure 61: DO Report in % saturation mode

Function Keys available in saturation report screen:

PRIN (F2)	Transfers calibration report to Computer through IrDA
NEXT (F3)	Goes to saturation measurement mode
ESC (F4)	Goes to saturation measurement mode
ENTER	(Not functional)
   	(Not functional)

3.11 DO Calibration in mg/L or ppm Concentration Mode

The amount of oxygen dissolved in a liquid will depend on its temperature, pressure and salinity. It is therefore very important to set temperature and salinity correctly before attempting to do a calibration. The PCD 650 is capable of measuring barometer pressure with its built-in pressure sensor. In the event, the pressure reading is inaccurate, you can calibrate the value from the Setup menu.

1. Switch on the meter. Make sure the meter is in concentration measurement mode.
2. Rinse the probe well with de-ionized rinse water. For best accuracy, blot the end of the probe dry. Dip the probe into a solution whose DO values is known. Do not touch the membrane.
3. Press **CAL (F2)** to go to calibration mode.

Note: If the meter is password protected, you will be prompted to enter a password. Refer 'Accessing Calibration mode when password protection enabled' in page 42.

4. The meter shows 'Dissolved O₂ Calibration-Rinse Electrode' screen [Figure 48-(a)] for few seconds to prompt user to rinse electrode with de-ionized water before calibration.




Figure 62 : Concentration calibration screens

5. The meter then shows the concentration calibration screen [Figure 62(a)].
6. The upper display of the calibration screen [Figure 62(b)] will show the current value of the measurement and the secondary display will show the value to which the meter is going to be calibrated. Press **▲** & **▼** keys to adjust the reading to the known oxygen concentration of the sample.
7. Press **ENTER** key to confirm the entered value.
8. Press **ESC (F4)** to go to measurement mode. The meter shows the concentration reading of the solution in measurement mode (Figure 63).




Figure 63 : Concentration calibration

Note: The function of the keys available on the concentration calibration/report screen is same as previously described in saturation calibration.

3.11.1 Concentration Calibration Report

Calibration report gives you information on calibrated temperature and calibration at pressure and salinity. It includes date & time on which the last calibration was done and the offset.

To View Concentration Report:

1. From concentration measurement mode, press left ◀ or right ▶ arrow key to navigate to other available functions until you see **REPO** function in the LCD.
2. Press **REPO (F2)** key. The calibration report is shown in the display [Figure 53].
3. Press **PRIN (F2)** to transfer the calibration report to the computer. (Refer page 37 to print data)




Figure 64 : DO report screen in mg/L mode

4. Setup Mode



4.1 About Setup Mode

The setup mode lets you configure various parameters & settings of the meter. You can choose to password-protect your settings, so that other users who may use the meter will not be able to change the settings.

Setup mode consists of the following sub-groups:

- **System** – General settings of the meter
- **pH/mV/Ion/Conductivity/TDS/Salinity/Resistivity/O₂ mg/L (ppm)/ O₂ (%)** – The pH/mV/Ion/Conductivity/TDS/Salinity/Resistivity's/O₂ mg/L (ppm)/ O₂ (%) Setup screen presents many options to control the operating parameters of their respective mode.
- **Temperature** - Temperature measurement & calibration related settings.

4.1.1 Accessing Setup mode (no password protection enabled)

1. Switch on the meter. The meter goes to measurement mode.
2. Press left  or right  arrow key on the keypad to navigate to other available functions until you see **SETUP** function in the LCD.
3. Press **SETP (F1)** and Setup Key Function screen appears. This page describes the keys functions for configuring various parameters and settings of the meter.




Figure 65: Setup Key Function screen

Note: If the meter is password protected, you will be prompted to enter a password before accessing Setup Key Function screen. Refer 'Accessing Setup mode when password protection enabled' in page 73 for details.

Function Keys available in setup key function screen:

▲ ▼	To select individual setup
ENTER	To select or confirm the selection.
NEXT-P	To navigate to next page.
NEXT	To go to next parameter without saving the changed parameter.
ESC	To go back to measurement mode.

4. Press **ENTER** key to select Setup Selection screen.
5. Press up ▲ or down ▼ arrow key to go to required setup sub-group.
6. Press **ENTER** key to select the currently shown sub-group.




Figure 66: Setup Selection screen

Function Keys available in setup selection screen:

(F1)	(Not functional)
(F2)	(Not functional)
(F3)	(Not functional)
▲ ▼	Goes to required setup sub-groups
ENTER	Selects the current sub-group
ESC (F4)	Goes to measurement mode from where you entered setup
◀ ▶	(Not functional)

4.1.2 Accessing Setup mode when password protection enabled

Follow the steps below to access the setup mode, when password protection is enabled.






1. Switch on the meter. The meter goes to measurement mode.
2. Press right arrow key  to navigate to other functions on the right-side of LCD.
3. Press **SETP (F1)** to go to Setup mode. Login password screen appears (Figure 67). The meter expects the 5-digit password specified in system setup. (Refer in page 80)





Figure 67: Login password screen

Note: You can enter '00000' (read-only password) if you wish to view the setup parameters. You are not allowed to modify any parameter when you enter 'read-only password'.



4. Press up  & down  arrow keys to enter the first digit of the password and then press **NEXT (F3)** key to move to the next digit.
5. The next digit is selected. Press up  & down  arrow keys to enter the second digit of the password. Enter all 5-digits.
6. Press **ENTER** key to confirm the password.

Note: If you enter an incorrect password, the screen shows 'Try again'. If an incorrect password is entered for 3 consecutive times, the meter goes to measurement mode. If you forget the password there is no way to access the system setting and calibration.





7. When the correct password is entered, the Setup Key Function Screen appears. (Figure 65)
8. Press **Enter** key to launch Setup Selection Screen. (See Figure 66)
9. Press up  or down  arrow key to go to required setup sub-group.
10. Press **ENTER** key to select the sub-group.

4.1.3 Modifying Setup parameters

Follow the steps below to modify setup parameters, when you enter a setup sub-group.

1. Press **NEXT (F3)** key to select individual setup parameters sequentially.
2. Press  (Up) or  (Down) arrow key to change the value of a selected parameter.
3. Once you changed a value:
 - Press **ENTER** key to save the change, or
 - Press **NEXT (F3)** key to go to the next parameter without saving the changed parameter.
4. Press **NEXT-P (F2)** or **PRE-P (F1)** to navigate to next or previous page.
5. Press **ESC (F4)** to exit from setup mode.

Function Keys available in setup sub-group screens:

PRE-P (F1)	Goes to the previous page of the same sub-group
NEXT-P (F2)	Goes to the next page of the same sub-group
NEXT (F3)	Goes to the next parameter of the same sub-group
ESC (F4)	Goes to measurement mode
 	Modify the selected parameter value
ENTER	Confirms/saves the changes made to the currently selected parameter and then goes to the next parameter of the same sub-group
 	(Not functional)

4.2 System Setup

System setup sub-group allows you to configure general settings of the meter. The settings are displayed in 6 pages. Press **NEXT-P (F2)** and **PREV-P (F1)** to navigate through these pages.

4.2.1 System Settings – Page 1



Figure 68: System Settings - Page 1

Parameter	Description	Factory Default
STABLE Indicator	ENABLE - The meter displays 'Stable' indicator in the measurement screen as per the 'STABLE CRITERIA' defined below. DISABLE – 'Stable' indicator does not appear.	ENABLE
Stability Criteria	SLOW – The reading is stabilized slowly and exhibits good repeatability MEDIUM – Reading stability is averaged between slow & fast stability FAST – Reading is stabilized quickly at the cost of repeatability. (This parameter has no effect if 'STABLE' parameter is disabled)	FAST
Auto Hold	ENABLE - The meter holds the reading in the measurement screen, if the reading is 'Stable' for consecutive 5 seconds. If this is enabled, 'Response time' appears in the measurement screen, indicating the average response time of the probe. DISABLE – The reading is not held (This parameter has no effect if 'STABLE' parameter is disabled. The response time may not work if the system time has not been set as described in page 77)	DISABLE

Tem. Display from	Allows to select temperature from pH/COND/DO probes to display in multi measurement screen.	-
For PCD 650-pH/COND->DO		
Display setting:-	Allows to select multi modes that you would like to be displayed on the 1 st , 2 nd and 3 rd row of the measurement screen after calibration.	-
	1 st Row : pH/Ion/mV/Conductivity/Salinity/Resitivity/TDS/O ₂ mg/L (ppm)/ O ₂ (%)	
	2 nd Row : pH/Ion/mV/Conductivity/Salinity/Resitivity/TDS/O ₂ mg/L (ppm)/ O ₂ (%)	
	3 rd Row : pH/Ion/mV/Conductivity/Salinity/Resitivity/TDS/O ₂ mg/L (ppm)/ O ₂ (%)	

4.2.2 System Settings – Page 2



Figure 69 : System Settings - Page 2

This page allows you to set the date & time of the meter.

Parameter	Description	Factory Default
Year	Sets the current year	2006
Month	Sets the current month	Jan
Date	Sets the current date	01
Hour	Sets the hour (24 Hours) for the current time	00
Minute	Sets the minute for the current time	00
Second	Sets the second for the current time	00

Note: The battery or DC adapter must always be connected to the meter for the system clock to run. The system time might be reset during the battery change. To prevent that happening, always connect the DC adapter during battery change.

Alternatively, if the DC adapter is not available, switch off the meter and change the batteries within **30** seconds to avoid resetting the clock.

4.2.3 System Settings – Page 3



Figure 70 : System Settings - Page 3

This page allows you to set auto-off and back light related parameters.

Parameter	Description	Factory Default
Auto OFF	ENABLE – Turns off the meter automatically if no key is pressed for the time period specified in 'ON TIME' below. DISABLE – Does not turns off the meter automatically	ENABLE
ON Time	After the last key is pressed, no. of minutes the meter should wait before automatically shuts down the meter. Maximum range: 30 min (This parameter has not editable if 'AUTO OFF' parameter is disabled)	10 min
Back Light (permanently ON)	ENABLE – Sets the back light always on. DISABLE – Sets the backlight always off.	DISABLE
Back Light ON with (Key press)	ENABLE – The back light of the LCD is automatically on when any key is pressed. DISABLE – Does not turn on the back light automatically.	DISABLE
ON time with (Key press)	Sets the meter to wait for specified number of minutes before automatically turning off the back light after the last key is pressed. (This parameter is not editable when 'BACK LIGHT (Key press)' is disabled) (This parameter has no effect if 'BACK LIGHT (Always)' parameter is set to ON)	1 min

Note: The above settings may not work if the system time has not been set as described in page 77.

4.2.4 System Settings – Page 4



Figure 71: System Settings - Page 4

This page allows you to set wireless serial data communication related parameters.

Parameter	Description	Factory Default
Print Mode	IrDA – Sets serial data communication protocol to IrDA LED – Sets serial data communication protocol to RS232C MEM- Logs data to meter's memory.	IrDA
Data Format	CyberComm – Select this format if you use CyberComm Data Acquisition Software (DAS) TEXT – Select this format if you use any other method (such as Windows® Hyperterminal) This parameter is used when downloading data from the meter through IrDA	CyberComm
Current Data Set	TIMED – Prints measurement data continuously at the interval specified in 'INTERVAL' parameter below. SINGLE – Prints only the currently measured reading This parameter applies when PRIN key is pressed from measurement mode to send the currently measured readings to the computer.	TIMED
Interval (3 Sec Step)	Time interval at which the meter should send currently measured data to the printer/CyberComm/PCD Acceptable range : 3 sec to 600 sec (in 3 sec steps)	9 Sec
Fixed Setting	(This parameter is applicable when 'CURRENT DATA SET' is set to 'TIMED' and this is not editable when 'CURRENT DATA SET' is set to 'SINGLE') Indicates serial communication settings in the format of 'Baud rate, Data bits-Parity bits-Stop bits'. This parameter is not editable.	2400 8-N-1

4.2.5 System Settings – Page 5

This page allows you to enable password protection for the setup mode & calibration mode.



Figure 72 : System Settings - Page 5

When you enable password protection, the meter prompts to enter the password whenever you try to access the Setup or Calibration mode. (See Figure 67: Login password screen). The meter does not allow you to edit setup parameters or perform a new calibration unless you enter the correct password. If an incorrect password is entered for 3 consecutive times, the meter goes to measurement mode.

Parameter	Description	Factory Default
Password Protection	<p>ENABLE – Sets password protection for the setup & calibration mode. If this is enable you need to specify a 5-digit password in the 'SET PASSWORD' parameter below</p> <p>DISABLE – Disable password protection of the meter</p>	DISABLE
Set Pass Word	<p>Specify your 5-digit password here. Use ▲ (Up) & ▼ (Down) key to select a number and then press ENTER key to confirm and move to the next digit.</p> <p>Do not set your password to '00000' as this is reserved for 'read-only' password. (This parameter is not editable when 'PASSWORD PROTECT' is disabled)</p>	88888
Confirm New Password	<p>YES – Select this if you have made changes to the password and you wish to confirm the changes.</p> <p>NO – Select this if you wish to ignore the changes made to the password and to store the default password.</p>	NO

Important:

1. Please memorize the password that you have entered after enabling the password protection because without entering password, neither you can disable the password protection or reset the meter to factory defaults. However, **if the user forgets his password, he can contact the nearest distributor or Eutech Instruments/Oakton Instruments to request for meter password.** This would be unique to each instrument and would be tied to the serial number of the unit.
2. Default password '88888' is valid only if it is not changed with new password.
3. You can enter '00000' (read-only password) if you wish to view the setup parameters. You are not allowed to modify any parameter when you enter 'read-only password'.

4.2.6 System Settings – Page 6**Figure 73 : System Settings - Page 6**

This page allows you to clear the memory and reset the meter to factory defaults.

Parameter	Description	Factory Default
Clear logged Data Memory	YES – Select this to clear all the stored data from the meter's memory NO – Select this if you do not wish to clear the stored data from the meter's memory	NO
Factory Reset	YES – Select this if you wish to reset the meter to its factory default settings. This includes: <ul style="list-style-type: none"> ▪ Deleting your calibration data ▪ Resetting setup parameters to factory defaults (except date & time) ▪ Deleting your stored data in the memory NO – Select this if you do not wish to reset the meter.	NO

When 'YES' is selected and confirmed by pressing ENETR key, the meter is reset to factory defaults and then the meter goes to measurement mode.

4.3 pH Setup

pH setup sub-group allows you to configure pH measurement & calibration related settings of the meter. The settings are displayed in 2 pages. Press **NEXT-P (F2)** and **PREV-P (F1)** to navigate through these pages.

4.3.1 pH Settings – Page 1




Figure 74: pH Settings - Page 1

This page allows you to set pH measurement & calibration related settings of the meter.

Parameter	Description	Factory Default
Buffer	Select your preferred pH standard buffer group for calibration & auto-recognition. Available groups: USA, NIST, DIN, PWB & USER Select 'USER' if you need to use a custom buffer for calibration.	USA
Cal points	Select the number of calibration points you intend to calibrate the meter using the selected buffer group. Available points: depends on the selected buffer group	3
Alarm Set Point	ENABLE – The measurement screen shows HI or LO alarm indicators when the meter reading is above 'HI alarm value' or below 'LO alarm value' specified in HI pH & LO pH parameters (below) DISABLE – HI and LO alarms are not shown in the LCD	DISABLE
Hi pH	Specify Hi alarm value here. The Hi alarm occurs when the pH reading goes above this value Available range: Hi pH (specified below) to 20.00 (This parameter is not editable when 'ALARM SET POINT' is disabled)	20.00pH
Lo pH	Specify Lo alarm value here. The Lo alarm occurs when the pH reading goes below this value Available range: 0.00 to Lo pH (specified above) (This parameter is not editable when 'ALARM SET POINT' is disabled)	0.00pH

4.3.2 pH Settings – Page 2




Figure 75: pH Settings - Page 2

Parameter	Description	Factory Default
pH Calibration Due	Specify number of days for the pH calibration alarm. The meter shows CAL DUE indicator after calibration due days are passed from the last calibration date. Available range: 0 to 30	5 Days
pH Resolution	Sets the resolution for pH measurement Available range: 0.1, 0.01, 0.001	0.00

☞ Press ▲ (Up) or ▼ (Down) arrow key to change pH measurement & calibration related settings of the meter.

4.4 mV setup (no settings available)

No settings are available for mV.




Figure 76: mV Setting Page

Press **ESC (F4)** to go to measurement mode.

4.5 Ion Setup

Ion setup sub-group allows you to configure Ion measurement & calibration related settings of the meter.

4.5.1 Ion Settings Page



Figure 77: Ion Settings Page

Parameter	Description	Factory Default
Ion unit	Sets the unit of measurement for Ion. Available units: ppm, molar and mg/L	ppm

☞ Press ▲ (Up) or ▼ (Down) arrow key to change the value of a selected parameter.

4.6 Conductivity Setup

Conductivity setup screen present many options to control the operating parameters, which can be controlled and set from the conductivity setup screen. The settings are displayed in 2 pages. Press **NEXT-P (F2)** and **PREV-P (F1)** to navigate through these pages.

4.6.1 Conductivity Settings – Page 1




Figure 78 : Conductivity Settings - Page 1

This page allows you to set operating parameters for the conductivity measurement mode:

Parameter	Description	Factory Default
Pure water Coeff.	Pure water coefficient will be calculated and applied automatically for ultra pure water measurement if enabled. (For more information, please refer page 87)	ENABLE
Lnr Temp Coefficient	Specify temperature coefficient to measure temperature corrected conductivity	2.100
Normalization Temp	Select a default temperature that the meter will use along with the temperature coefficient to calculate a temperature corrected conductivity measurement.	25
Cell Constant	Select the appropriate cell constant of the conductivity cell. Available cell constants: 0.1 to 10	1.000
Calibration due	Specify number of days for the Conductivity calibration alarm. The meter shows CAL DUE indicator after calibration date. Available range : 0 to 30 (if enabled)	DISABLE
Calibration points	Single - In single point calibration one calibrated conductivity value can be used for the entire 5 conductivity ranges. Multi - In multi point calibration, you can calibrate one point in each of the measuring ranges (up to 5 points.)	Single
Calibration mode	AUTO - In the automatic calibration mode, the meter automatically detects and verifies the appropriate known calibration standards solutions. Manual - In the manual calibration, you can manually input the appropriate values as your desired calibration standards in each specific range.	Auto

Note: 1. If pure water coefficient is '**ENABLE**', the meter will apply pure water compensation automatically below 2 μS and switch back to linear compensation for above 2 μS .

2. If pure water coefficient is '**DISABLE**', Lnr Temp Coefficient applies throughout the measurement.

4.6.2 Conductivity Settings – Page 2




Figure 79 : Conductivity Settings - Page 2

This page allows you to set alarm limits for the conductivity measurement mode. A visual alarm symbol will appear on the screen, if the conductivity value of the measurement is outside of the boundaries set by the minimum and maximum limits.



Parameter	Description	Factory Default
Alarm Set Points	Set alarm limits for the conductivity measurement mode: ENABLE – The measurement screen shows HI or LO alarm indicators when the meter reading is above 'HI alarm value' or below 'LO alarm value' specified in HI & LO μS parameters (below) DISABLE – HI and LO alarms are not shown in the LCD	DISABLE
Hi μS	Specify Hi alarm value here. The Hi alarm occurs when the conductivity reading goes above this value Available range: Hi μS (specified below) to 2.000 μS (This parameter is not editable when 'ALARM SET POINT' is disabled)	2.000 μS
Lo μS	Specify Lo alarm value here. The Lo alarm occurs when the conductivity reading goes below this value Available range: 1.00 μS to Hi μS (specified above) (This parameter is not editable when 'ALARM SET POINT' is disabled)	1.000 μS

4.7 TDS Setup

TDS setup screen present many options to control the operating parameters, which can be controlled and set from the TDS setup screen. The settings are displayed in 2 pages. Press **NEXT-P (F2)** and **PREV-P (F1)** to navigate through these pages.

4.7.1 TDS Settings – Page 1




Figure 80 : TDS Settings - Page 1

This page allows you to set operating parameters for TDS measurement mode:

Parameter	Description	Factory Default
The Pure water coeff, Lnr Temp Coefficient, normalization temperature, cell constant, calibration due, calibration points are set the same way as previously described in Conductivity set up. See 'Conductivity Settings – Page 1' on page 86.		
TDS factor	The TDS conversion factor is the number used by the meter to convert from conductivity to TDS. The TDS conversion factor automatically adjusts the reading. The TDS conversion factor can be set from 0.40 to 1.00. For more information on TDS refer pages 27 and 106	0.500

NOTE: The factory default setting for the TDS conversion factor is 0.50.

4.7.2 TDS Settings – Page 2




Figure 81 : TDS Settings - Page 2

This page allows you to set alarm limits for the TDS measurement mode:

Parameter	Description	Factory Default
Alarm Set Points	Set alarm limits for the TDS measurement mode: ENABLE – The measurement screen shows HI or LO alarm indicators when the meter reading is above 'HI alarm value' or below 'LO alarm value' specified in HI & LO ppm parameters (below) DISABLE – HI and LO alarms are not shown in the LCD	DISABLE
Hi ppm	Specify Hi alarm value here. The Hi alarm occurs when the TDS reading goes above this value Available range: Hi ppm to 2.00 ppm (This parameter is not editable when 'ALARM SET POINT' is disabled)	2.00 ppm
Lo ppt	Specify Lo alarm value here. The Lo alarm occurs when the TDS reading goes below this value Available range: 1.00 ppt to Hi ppm (specified above) (This parameter is not editable when 'ALARM SET POINT' is disabled)	1.00 ppt

☞ Press ▲ (Up) or ▼ (Down) arrow key to set high or low alarm point.

4.8 Salinity Setup

Salinity setup screen present many options to control the operating parameters, which can be controlled and set from the salinity setup screen. The settings are displayed in 2 pages. Press **NEXT-P (F2)** and **PREV-P (F1)** to navigate through these pages.

4.8.1 Salinity Settings – Page 1




Figure 82: Salinity Settings - Page 1

This page allows you to set operating parameters for salinity measurement. The Pure water coeff, Lnr Temp Coefficient, normalization temperature, cell constant, calibration due, calibration points are set the same way as previously described in Conductivity set up. See 'Conductivity Settings – Page 1' on page 86.

4.8.2 Salinity Settings – page 2




Figure 83: Salinity Settings - Page 2

This page allows you to set alarm limits for the salinity measurement mode:

Parameter	Description	Factory Default
Alarm Set Points	Set alarm limits for the salinity measurement mode: ENABLE – The measurement screen shows HI or LO alarm indicators when the meter reading is above 'HI alarm value' or below 'LO alarm value' specified in HI & LO <i>ppm</i> parameters (below) DISABLE – HI and LO alarms are not shown in the LCD	DISABLE
Hi ppm	Specify Hi alarm value here. The Hi alarm occurs when the salinity reading goes above this value Available range: Hi ppm to 2.00 ppm	2.00 ppm
Lo ppt	Specify Lo alarm value here. The Lo alarm occurs when the salinity reading goes below this value Available range: 1.00 to Hi <i>ppm</i> (specified above) (This parameter is not editable when 'ALARM SET POINT' is disabled)	1.00 ppt

☞ Press ▲ (Up) or ▼ (Down) arrow key to set high or low alarm point.

4.9 Resistivity Setup

Resistivity setup screen present many options to control the operating parameters, which can be controlled and set from the resistivity setup screen. The settings are displayed in 2 pages. Press **NEXT-P (F2)** and **PREV-P (F1)** to navigate through these pages.

4.9.1 Resistivity Settings – Page 1




Figure 84: Resistivity Settings - Page 1

This page allows you to set operating parameters for resistivity measurement mode. The Pure water coeff, Lnr Temp Coefficient, normalization temperature, cell constant, calibration due, calibration points are set the same way as previously described in Conductivity set up. See 'Conductivity Settings – Page 1' on page 86.

4.9.2 Resistivity Settings – Page 2




Figure 85: Resistivity Settings - Page 2

This page allows you to select alarm limits for resistivity measurement mode.

Parameter	Description	Factory Default
Alarm Set Points	Set alarm limits for the resistivity measurement mode: ENABLE – The measurement screen shows HI or LO alarm indicators when the meter reading is above 'HI alarm value' or below 'LO alarm value' specified in HI & LO Ω parameters (below) DISABLE – HI and LO alarms are not shown in the LCD	DISABLE
Hi Ω	Specify Hi alarm value here. The Hi alarm occurs when the resistivity reading goes above this value Available range: Lo Ω to 20.00 M Ω ohm (This parameter is not editable when 'ALARM SET POINT' is disabled)	2.00 Ω
Lo Ω	Specify Lo alarm value here. The Lo alarm occurs when the resistivity reading goes below this value Available range: 0.000 to Hi Ω (This parameter is not editable when 'ALARM SET POINT' is disabled)	1.00 Ω

☞ Press  (Up) or  (Down) arrow key to set high or low alarm point.

4.10 O₂ % - DO Saturation Setup

DO saturation (%) setup screen present many options to control the operating parameters, which can be controlled and set from the DO setup screen. The settings are displayed in 2 pages. Press **NEXT-P (F2)** and **PREV-P (F1)** to navigate through these pages.

4.10.1 DO (%) – Page 1



Figure 86 : DO (%) – Page 1

Parameter	Function	Factory Default
Offset Cal	Allows to adjust % saturation offset calibration	0.0 %
Calibration due	Specify number of days for the DO calibration alarm. The meter shows CAL DUE indicator after calibration date.	5 days
	Available range : 0 to 30	
Select Pressure Unit	Sets the unit for barometric pressure Available units: mmHg and kPa	mmHg
Measured Pressure	Barometric pressure as measured by the instrument.	
Adjusted Pressure	User adjusted value.	-
Pressure Compensation	ENABLE – The meter will compensate for the barometric pressure at the location depending on the altitude. DISABLE – No compensation for the pressure.	ENABLE
	(This is applicable only for the % saturation mode. For mg/L or ppm mode pressure comp. would always be applicable)	

NOTE: During measurement, the PCD 650 will automatically measure and compensate for barometric pressure. However, if the user feels that barometric pressure is inaccurate and needs to be calibrated, it can be adjusted in the DO setup screen.

4.10.2 DO (%) – Page 2



Figure 87: DO (%) - Page 2



This page allows you to set alarm limits for the DO saturation measurement mode. A visual alarm symbol will appear on the screen, if the DO value of the measurement is outside of the boundaries set by the minimum and maximum limits.

Parameter	Function	Factory Default
DO Alarm	Set alarm limits for the DO measurement modes: ENABLE – The measurement screen shows HI or LO alarm indicators when the meter reading is above 'HI alarm value' or below 'LO alarm value' specified in HI & LO % parameters (below) DISABLE – HI and LO alarms are not shown in the LCD	DISABLE
Hi DO %	Specify Hi alarm value here. The Hi alarm occurs when the DO reading goes above this value (This parameter is not editable when 'ALARM SET POINT' is disabled)	200.0 %
Lo DO%	Specify Lo alarm value here. The Lo alarm occurs when the DO reading goes below this value (This parameter is not editable when 'ALARM SET POINT' is disabled)	10.0 %

4.11 O₂ mg/L (ppm) – DO Concentration Setup

DO Concentration (mg/L) setup screen present many options to control the operating parameters, which can be controlled and set from the DO setup screen. The settings are displayed in 2 pages. Press **NEXT-P (F2)** and **PREV-P (F1)** to navigate through these pages.

4.11.1 DO (mg/L) – Page 1




Figure 88 : DO (mg/L) – Page 1

This page allows you to set operating parameters for the DO Concentration measurement mode:

Parameter	Function	Factory Default
Select DO Unit	Sets the unit of measurement for DO	mg/L
	Available units: mg/L and ppm	
Auto Salinity Comp	DISABLE – No automatic compensate ENABLE – The meter will apply measured salinity for DO concentration of your sample.	DISABLE
	Note: This option is activated only in CD650 & PCD650.	
Set Salinity	Allows to set the salinity (in ppt) for your solution	0.0 ppt
	Available range: 0 to 50 ppt	

NOTE: Auto salinity compensation will be applicable only in multi measurement mode and only if one of the measurement selected is conductivity related. Otherwise, manually set salinity value will be applied.

4.11.2 DO (mg/L) – Page 2




Figure 89: DO (mg/L) – Page 2



This page allows you to set alarm limits for the DO concentration mode. A visual alarm symbol will appear on the screen, if the DO value of the measurement is outside of the boundaries set by the minimum and maximum limits.

Parameter	Function	Factory Default
DO Alarm	Set alarm limits for the DO measurement modes: ENABLE – The measurement screen shows HI or LO alarm indicators when the meter reading is above 'HI alarm value' or below 'LO alarm value' specified in HI & LO % parameters (below) DISABLE – HI and LO alarms are not shown in the LCD	DISABLE
Hi DO mg/L	Specify Hi alarm value here. The Hi alarm occurs when the DO reading goes above this value (This parameter is not editable when 'ALARM SET POINT' is disabled)	20.0 mg/L
Lo DO mg/L	Specify Lo alarm value here. The Lo alarm occurs when the DO reading goes below this value (This parameter is not editable when 'ALARM SET POINT' is disabled)	1.0 mg/L

4.12 Temperature Setup

Temperature setup sub-group allows you to configure temperature measurement & calibration related settings of the meter.

4.12.1 Temperature Setting Page




Figure 90 : Temperature Settings Page

Parameter	Description	Factory Default
Unit	Sets the unit of measurement for temperature. Available units: °C and °F	°C
Mode	Sets the temperature compensation mode. ATC – Automatic Temperature Compensation MTC – Manual Temperature Compensation	ATC

☞ Press ▲ (Up) or ▼ (Down) arrow key to change unit of measurement and temperature compensation mode.

5. Technical Specifications

Model		PCD 650 meter		
pH				
Range		-2.000 to 20.000 pH		
Resolution		0.1/0.01/0.001 pH		
Relative Accuracy		± 0.002 pH + 1 LSD		
No. of Calibration points		1 (offset) to 6 points		
No. of Buffer Options		15		
Calibration due alarm		User configurable (up to 30 days)		
Set point alarm		User configurable		
Auto buffer recognition		Yes		
pH buffer Groups & Calibration Points		USA : 1.68, 4.01, 7.00, 10.01, 12.45 NIST: 1.68, 4.01, 6.86, 9.18, 12.45 DIN : 1.09, 3.06, 4.65, 6.79, 9.23, 12.74 PWB : 4.10, 6.97		
Calibration Window				
USA		± 1.5 pH (for 7.00pH), ±1 pH (for all other buffers)		
NIST		± 1.35 pH (for 6.86pH), ±1 pH (for all other buffers)		
DIN		± 0.8 pH (for 1.09, 3.06, 4.65pH), ±1 pH (for 9.23, 12.74pH), ±1.34 pH (for 6.79pH)		
PWB		± 0.8 pH		
Custom buffer calibration		Yes (2 to 5)		
Slope/Offset display		Yes (Display + Icon)		
mV				
Range		± 2000.0mV		
Resolution		0.1 mV		
Relative Accuracy		± 0.2 mV + 1 LSD		
Ion				
Range		0.001 to 19900		
Units		ppm, molar, mg/L		
Resolution		2 or 3 digits		
Relative Accuracy		0.5% FS (monovalent) 1% FS (divalent)		
Temperature				
Range		-10.0 °C to 110.0 °C (14.0 °F to 230.0 °F)		
Resolution		0.1 °C/ 0.1 °F		
Relative Accuracy		± 0.5 °C / ± 0.9 °F		
Temp. Input Connector		8-pin Round		
Temperature Sensor		30K Thermistor		
Conductivity				
Range	Measuring ranges	Resolution	Sub range Accuracy	Cal Standards

1	0.050uS to 2.000uS	0.01uS*	1% of FS	No
2	2.000uS to 9.990 uS	0.01uS*	1% of FS	84.00uS
	10.00uS to 99.99uS	0.01uS	1% of FS	
	100.0uS to 300.0uS	0.1uS	1% of FS	
3	300.0uS to 999.9uS	0.1uS	1% of FS	1.413mS
	1.000mS to 4.000mS	0.001mS	1% of FS	
4	4.000mS to 9.999mS	0.001mS	1% of FS	12.88mS
	10.00mS to 40.00mS	0.01mS	1% of FS	
5	40.00mS to 99.99mS	0.01mS	1% of FS	111.8mS
	100.0mS to 500.0mS	0.1mS	1% of FS	
* Display resolution is 0.001				

TDS at TDS factor 1.000

Range	Measuring ranges	Resolution	Sub range Accuracy
1	0.050ppm to 2.000ppm	0.01ppm*	1% of FS
2	2.000ppm to 9.990 ppm	0.01ppm*	1% of FS
	10.00ppm to 99.99ppm	0.01ppm	1% of FS
	100.0ppm to 300.0ppm	0.1ppm	1% of FS
3	300.0ppm to 999.9ppm	0.1ppm	1% of FS
	1.000ppt to 4.000ppt	0.001ppt	1% of FS
4	4.000ppt to 9.999ppt	0.001ppt	1% of FS
	10.00ppt to 40.00ppt	0.01ppt	1% of FS
5	40.00ppt to 99.99ppt	0.01ppt	1% of FS
	100.0ppt to 500.0ppt	0.1ppt	1% of FS
* Display resolution is 0.001			

Salinity

Range	Measuring ranges	Resolution	Sub range Accuracy
1	0.020ppm to 0.770ppm	0.01ppm*	1% of FS
2	0.770ppm to 9.990 ppm	0.01ppm*	1% of FS
	10.00ppm to 99.99ppm	0.01ppm	1% of FS
	100.0ppm to 143.3ppm	0.1ppm	1% of FS
3	143.3ppm to 999.9ppm	0.1ppm	1% of FS
	1.000ppm to 2.138ppt	0.001ppt	1% of FS
4	2.138ppt to 9.999ppt	0.001ppt	1% of FS
	10.00ppt to 23.64ppt	0.01ppt	1% of FS
5	23.64ppt to 80.00ppt	0.01ppt	1% of FS
* Display resolution is 0.001			

Resistivity

Range	Measuring ranges	Resolution	Sub range Accuracy
5	10.00MΩ to 20.00MΩ	0.01MΩ	1% of FS
	1.000MΩ to 9.999MΩ	0.001MΩ	1% of FS

4	500.0KΩ to 999.9KΩ	0.1KΩ	1% of FS
	100.0KΩ to 500.0KΩ	0.1Ω	1% of FS
	10.00KΩ to 99.99KΩ	0.01Ω	1% of FS
	3.333KΩ to 9.999KΩ	0.001Ω	1% of FS
3	1.000KΩ to 3.333KΩ	0.001Ω	1% of FS
	250.0Ω to 999.9Ω	0.1Ω	1% of FS
2	100.0Ω to 250.0Ω	0.1Ω	1% of FS
	25.00Ω to 99.99Ω	0.01Ω	1% of FS
1	10.00Ω to 25.00Ω	0.01Ω	1% of FS
	2.000Ω to 9.990Ω	0.01Ω*	1% of FS
* Display resolution is 0.001			
Conductivity/ TDS / Salinity/ Resistivity			
Conductivity Range		0 to 500 mS	
Salinity		80 ppt	
Resistivity		0 to 20.00MΩ	
TDS		500 ppt	
Conductivity Cell constant		0.010 to 10.000	
Conductivity Cell		2 & 4 Cell	
TDS Conversion Factor		0.400 to 1.000	
Temperature Comp.		Linear & Pure	
Cal-Auto/Manual		Yes	
Cal-Single/Multi		Yes	
Cal Due Alarm		Yes (max-30 days)	
Set Point Alarm		Yes	
Input Conductivity		BNC / 8 Pin Round	
Display			
Display type		Dot matrix LCD with backlighting	
Screen resolution		110 x 128	
Viewing area		68 x 74 mm	
Backlit		Yes	
Other			
Data logging		500 data sets	
Data communication		IrDA / RS232C-Infrared	
Auto Data logging (only to PC)		Yes	
GLP (Good Lab Practice)		Yes	
Ingress protection		IP 67	
Dimensions		95mm (W) x 185mm (L) x 58.5mm (H) - Without Rubber Boot 101mm (W) x 191mm (L) x 61mm (H) - With Rubber Boot	
Weight		380g (Without Rubber Boot)	
Power Input			
Battery		4 x Alkaline AA size, 1.5 V	
Batter Life		200 Hrs (without backlight & serial data transfer)	
Power adapter		Input: 100-240V AC Output: DC 9-12V, 6W Max	

6. Accessories

6.1 Replacement Accessories

Eutech Instruments

Product Description	Eutech Instruments Order Code
Rubber Boot for 600 series meters	OKRUBBERBT600
100-240VAC Power Adapter	01X030132

6.2 Optional Accessories

Eutech Instruments

Product Description	Eutech Instruments Order Code
8 pin connector Temperature probe (3m Cable)	ECPHWPTM03J
8 pin connector Temperature probe (1m Cable)	ECPHWPTM01J
General Purpose Plastic-Body, Double Junction, Ag/AgCl pH electrode (3m Cable)	ECFC7252203B
General Purpose Plastic-Body, Double Junction, Ag/AgCl pH electrode (1m Cable)	ECFC7252201B
General Purpose Plastic-Body, 3-in-1, pH/Temp Ag/AgCl pH electrode (1m Cable)	ECFC7352901J
2 Stainless Steel Rings Ultem-body Electrode with ATC (3m cable length)	ECCONSEN9103J
4-cell, Graphite, Epoxy-body Electrode with ATC (3m cable length)	ECCONSEN9203J
Galvanic Dissolved Oxygen probe with ATC (3m cable length)	ECDOHANDYNEW
Membrane & O-ring (pack of 5)	01X241603
Assembled Membrane Cap Housing	15X241402
Membrane removal tool	15X241502
Electrode Guard Removal Tool	15X241504
DO Refilling electrolyte, 60 mL	01X211226

Oakton Instruments

Product Description	Oakton Instruments Order Code
8 pin connector Temperature probe (3m Cable)	35418-07
8 pin connector Temperature probe (1m Cable)	35418-05
General Purpose Plastic-Body, Double Junction, Ag/AgCl pH electrode (OKFC7252203B, 3m Cable)	35816-77

General Purpose Plastic-Body, Double Junction, Ag/AgCl pH electrode (1m Cable)	35641-51
General Purpose Plastic-Body, 3-in-1,pH/Temp Ag/AgCl pH electrode (1m Cable)	35816-71
2-cell Electrode with ATC, cell constant K=1.0 (OKCONSEN9103J, 3m cable)	35408-57
2-cell Electrode with ATC, cell constant K=1.0	35408-52
4-cell Electrode with ATC, cell constant K=0.3	35408-56
2-cell Electrode with ATC, cell constant K=10.0	35408-54
2-cell Electrode with ATC, cell constant K=0.1	35408-50

Oakton Instruments

Product Description (Dissolved Oxygen)	Oakton Instruments Order Code
Galvanic Dissolved Oxygen probe with ATC with 10-ft cable	35640-50
Galvanic Dissolved Oxygen probe with ATC 25-ft cable	35640-52
Galvanic Dissolved Oxygen probe with ATC 50-ft cable	35640-54
Galvanic Dissolved Oxygen probe with ATC 100-ft cable	35640-56
Replacement batteries, AA. Pack of 4	09376-01
Replacement DO membranes, Pack of 5.	35640-74
Replacement DO membranes, Pack of 25.	35640-75
Replacement membrane kit; two membrane caps and one bottle of electrolyte solution	35640-80
Assembled Membrane Cap Housing	35640-72
Membrane removal tool	35640-79
Zero oxygen solution, 500 mL	00653-00
DO Refilling electrolyte , 500 mL	35640-71
Electrolyte DO powder (58.5 g)	35640-70
Rubber Boot for 600 series meters	35418-86
100-220VAC Power Adapter	35418-83
Carrying Case with 4 sets of empty 60 ml bottle	35632-99

7. APPENDIX

7.1 Conductivity theory

Conductance is a quantity associated with the ability of primarily aqueous solutions to carry an electrical current, I , between two metallic electrodes when a voltage E is connected to them. Though water itself is a rather poor conductor of electricity, the presence of ions in the water increases its conductance considerably, the current being carried by the migration of the dissolved ions. This is a clear distinction from the conduction of current through metal, which results from electron transport. The conductance of a solution is proportional to and a good, though nonspecific indicator of the concentration of ionic species present, as well as their charge and mobility. It is intuitive that higher concentrations of ions in a liquid will conduct more current. Conductance derives from Ohms law, $E = IR$, and is defined as the reciprocal of the electrical resistance of a solution.

$$C = 1/R \quad C \text{ is conductance (siemens)} \quad R \text{ is resistance (ohms)}$$

One can combine Ohms law with the definition of conductance, and the resulting relationship is:

$$C = I/E \quad I \text{ is current (amps)} \quad E \text{ is potential (volts)}$$

In practice, conductivity measurements involve determining the current through a small portion of solution between two parallel electrode plates when an ac voltage is applied. Conductivity values are related to the conductance (and thus the resistance) of a solution by the physical dimensions - area and length - or the cell constant of the measuring electrode. If the dimensions of the electrodes are such that the area of the parallel plates is very large, it is reasonable that more ions can reside between the plates, and more current can be measured. The physical distance between the plates is also critical, as it affects the strength of the electric field between the plates. If the plates are close and the electric field is strong, ions will reach the plates more quickly than if the plates are far apart and the electric field is weak. By using cells with defined plate areas and separation distances, it is possible to standardize or specify conductance measurements.

Thus derives the term specific conductance or conductivity.

The relationship between conductance and specific conductivity is:

$$\text{Specific Conductivity, S.C.} = (\text{Conductance}) (\text{cell constant, } k) = \text{siemens} * \text{cm/cm}^2 = \text{siemens/cm}$$

$$C \text{ is the Conductance (siemens)} \quad k \text{ is the cell constant, length/area or cm/cm}^2$$

Since the basic unit of electrical resistance is the ohm, and conductance is the reciprocal of resistance, the basic unit of conductance was originally designated a "mho"- ohm spelled backwards - however, this term has been replaced by the term "siemen". Conductivity measurements are reported as Siemens/cm, since the value is measured between opposite faces of a cell of a known cubic configuration. With most aqueous solutions, conductivity quantities are most frequently measured in micro Siemens per cm ($\mu\text{S/cm}$) or mill Siemens per cm (mS/cm).

The PCD 650 series meter not only measures conductivity readings from micro or milli Siemens but also reads resistivity (Ohms, kOhms and MOhms), TDS (ppm and ppt), and salinity (ppt).

The salinity scale which ranges from 0 to 80 ppt is a measure of all salts, not just sodium chloride. This scale was originally devised for seawater, and is based on seawater at 15 degrees Centigrade has a conductivity equivalent to that of a potassium chloride solution of a known concentration. This solution (0.44 molar) is defined as having a salinity of 35 ppt.

Note: ppm = parts per million, ppt = parts per thousand, 1000 ppm = 1 ppt

The total dissolved solids scale approximates the ppm TDS in surface waters by multiplying the conductivity of a sample by a factor, 0.66.

Some users prefer the use of resistivity units to describe their water, particularly where high purity water is involved. The unit most often used to describe resistivity is megohm•cm., which is simply the reciprocal of conductivity ($\mu\text{S}/\text{cm}$). The chart below shows the relationship between these units.

Conductivity, $\mu\text{S}/\text{cm}$	Resistivity, megohm. cm
0.056	18.0
0.1	10.0
1.0	1.0
2.5	0.4
10.0	0.1

Conductivity and Temperature

Conductivity in aqueous solutions reflects the concentration, mobility, and charge of the ions in solution. The conductivity of a solution will increase with increasing temperature, as many phenomena influencing conductivity such as solution viscosity are affected by temperature.

The relationship between conductivity and temperature is predictable and usually expressed as relative % change per degree centigrade. This temperature coefficient (% change per degree) depends on the composition of the solution being measured. However, for most medium range salt concentrations in water, 2% per degree works well. Extremely pure water exhibits a temperature coefficient of 5.2%, and concentrated salt solutions about 1.5%.

This meter permit you to enter the temperature coefficient which best suits your sample and use an ATC probe to automatically temperature compensate back to the chosen reference temperature.

It is important to choose an electrode with an appropriate cell constant. The following table lists the optimum conductivity ranges for electrodes with cell constants of 0.1, 1, and 10.

Cell Constant	Optimum Conductivity Range, 2-cell	Optimum Conductivity Range, 4-cell
0.1	0.5 to 200 $\mu\text{S}/\text{cm}$	Not Available
1.0	0.01 to 2 mS/cm	0.01 to 20 mS/cm
10.0	1 to 200 mS/cm	1 to 200 mS/cm

7.2 Calculating TDS Conversion Factor

You can calibrate your meter using TDS calibration standard solutions. The calibration standard only needs to give the TDS value at a standard temperature such as 25 °C. To determine the conductivity-to-TDS conversion factor use the following formula:

$$\text{Factor} = \text{Actual TDS} \div \text{Actual Conductivity @ 25 °C}$$

Definitions:

Actual TDS: Value from the solution bottle label or as a standard you make using high purity water and precisely weighed salts.

Actual Conductivity: Value measured using a properly calibrated Conductivity/Temperature meter.

Both the Actual TDS and the Actual Conductivity values must be in the same magnitude of units. For example, if the TDS value is in ppm the conductivity value must be in µS; if the TDS value is in ppt the conductivity value must be in mS.

Check your factor by multiplying the conductivity reading by the factor in the above formula. The result should be in TDS value.

7.3 Calculating Temperature Coefficients

To determine the temperature coefficient of your sample solution use this formula:

$$tc = 100 \times \frac{C_{T2} - C_{T1}}{C_{T1}(T_2 - 25) - C_{T2}(T_1 - 25)}$$

Where:

tc = Temperature coefficient **25** = 25 °C

C_{T1} = Conductivity at Temp 1 **C_{T2}** = Conductivity at Temp 2

T₁ = Temp 1 **T₂** = Temp 2

NOTE: A controlled temperature water bath is ideal for this procedure.

1. Immerse the probe into a sample of your solution and adjust the temperature coefficient to 0%
2. Wait for 5 minutes. Note **T₁** and **C_{T1}** (conductivity at **T₁**).
3. Condition the sample solution and probe to a temperature (**T₂**) that is about 5 °C to 10 °C different from **T₁**, and note the conductivity reading **C_{T2}**.

NOTE: Record your results for future reference. Ideally **T₁** and **T₂** should bracket your measurement temperature, and should not differ by more than 5 °C.

7.4 Dissolved Oxygen Probe

7.4.1 Dissolved Oxygen Principle

The probe is a galvanic measuring element which produces an output proportional to the oxygen present in the medium in which it is placed. The galvanic probe design lets you take measurements immediately – without the typical 15 minute wait of other dissolved oxygen probes.

The probe consists of two parts:

- An upper part consisting of an anode, a cathode, and cable.
- A lower part consisting of a membrane cap, membrane, and electrolyte solution.

Oxygen diffuses through the membrane onto the cathode, where it is consumed. This process produces an electrical current which flows through the cable to the meter. The electric current produced is proportional to the oxygen that passes through the membrane and the layer of electrolyte. This makes it possible to measure the partial pressure of oxygen in the sample at a given temperature.

Since the DO in the sample is consumed by the cathode it is essential that a new sample must flow past the membrane of the probe to prevent the occurrence of false readings. The probe uses very little oxygen for its measurement. This enables it to function correctly with liquid movement as low as 2.5 cm/sec.

The permeability of the membrane to oxygen varies greatly with temperature. Therefore compensation is needed for this variation. The DO probe comes with an in-built Temperature Compensation for the membrane variation.

7.4.2 Probe Care

Under typical operating conditions, the probe should last for several years. Proper care and maintenance will help you receive the maximum probe life and ensure more accurate readings.

Since any deposits on the membrane surface act as a barrier to oxygen diffusing through the membrane, the membrane must be cleaned at regular intervals to assure maximum reliability.

After using the probe, rinse the probe in clean water and wipe it with a soft cloth or paper to avoid any hardening of deposits. If growth develops on the probe, use a disinfecting chemical to clean.

NOTE: Although the membrane is strong and not easily damaged, wipe it gently while cleaning it. If the membrane is damaged or torn, the probe will no longer function.

There are no special probe storage requirements.

7.4.3 Membrane Housing Replacement

Replacement of the membrane cap housing/ membrane is required only when you cannot calibrate the probe, or if the membrane is damaged.

Typical membrane damages are punctures or wrinkles caused during measurements or cleaning.

Your new DO probe comes with replacement membrane housing. To order more replacement membrane housing, see the “Accessories” section page.

To replace the membrane cap (with pre-installed membrane)

1. Replacement is much easier with single membrane housing. Unscrew the old membrane cap housing.
2. Hold the probe under hot running water and brush away the white oxide on the cylindrical anode with a stiff plastic brush – do not use metal cleaning material.
3. If the cathode has any deposits, remove them with a light scouring powder. Do not polish the cathode.
4. Fill the new membrane cap housing with electrolyte solution and inspect the bottom for leaks. If the solution drops are leaking from the membrane, use new cap housing.
5. If the assembly is leak-free, fill the membrane cap housing with electrolyte to the brim.
6. Tap the side of the housing gently to remove any air bubble that may be sticking to the membrane.
7. Screw the cap onto the probe. Excess electrolyte will drain out.
8. Replace probe guard.
9. Calibrate the probe after the % saturation readings have stabilised.




Figure 91:
Positioning of O-ring & membrane




Figure 92: Positioning
of O-ring & membrane

7.4.4 Membrane/O-ring Replacement (Optional Procedure)

It is recommended only experienced service personnel can perform this procedure.

This procedure is OPTIONAL, and should only be performed if you have new membrane and O-ring. You are also required to have a membrane installation tool. These items are available as optional accessories in the “Accessories” section.

Pull off the probe guard.

1. Unscrew the membrane cap from the probe.

2. Hold the probe under hot running water and brush away the white oxide on the cylindrical anode with a stiff plastic brush – do not use metal cleaning material.
3. If the cathode has any deposits, remove them with a light scouring powder. Do not polish the cathode.
4. Using the installation tool, unscrew and remove the membrane lock from the membrane cap. See Figure 93 on the following page.
5. Remove the membrane and O-ring. Discard both.
6. Rinse the membrane cap and membrane lock in tap water.
7. Install a new O-ring inside the membrane cap.
8. Install a new membrane. Make sure the membrane covers the O-ring all around its circumference.
9. Using the installation tool, screw the membrane lock back into the cap. Tighten the lock firmly over the membrane and O-ring, but do not over tighten.
10. Inspect the membrane for wrinkles. If wrinkles exist, remove the membrane and repeat steps 8 – 11.
11. Fill the membrane cap with water and inspect the bottom for leaks. If water drops are leaking from the membrane, re-seal the membrane on the O-ring (repeat steps 8 – 11, for membrane replacement only).

If the assembly is leak-free, empty the water and fill the membrane cap with electrolyte to the brim.

12. Tap the side of the housing gently to remove any air bubble that may be sticking to the membrane.
13. Screw the cap onto the probe. Excess electrolyte will drain out.
14. Replace probe guard.
15. Calibrate the probe after the % saturation readings have stabilised.

Note: Membranes can only be used once. When a membrane cap is screwed onto the probe, the membrane is stretched by the cathode. If the same O-ring and the membrane is used a second time it will not fit perfectly onto the cathode. This will result in erratic readings.

7.4.5 Electrolyte Solution

The electrolyte solution in your probe's cap will deplete on usage and will need to be replaced periodically.

Your new DO probe comes with accessories of one replacement electrolyte solution and a spare membrane cap. The replacement electrolyte comes premixed and ready to use. To order more electrolyte solution, see "Accessories" section.




Figure 93: Use Tool to take out (or put in) membrane

8. General Information

8.1 Warranty

Eutech Instruments supplies this meter with a 3-year warranty and 6-month warranty for electrode against manufacturing defects from the date of purchase. If repair or adjustment is necessary and has not been the result of abuse or misuse within the designated period, please return – freight pre-paid – and correction will be made without charge. Eutech Instruments/ Oakton Instruments will determine if the product problem is due to deviations or customer misuse.

Out of warranty products will be repaired on a charged basis.

Exclusions

The warranty on your instrument shall not apply to defects resulting from:

- Improper or inadequate maintenance by customer
- Unauthorized modification or misuse
- Operation outside of the environment specifications of the products

8.2 Return of Goods

Before returning goods for any reason whatsoever, the Customer Service Dept. has to be informed in advance. Items must be carefully packed to prevent damage during shipment, and insured against possible damage or loss. Eutech Instruments/ Oakton Instruments will not be responsible for any damage resulting from careless or insufficient packing.

Warning: Shipping damage as a result of inadequate packaging is the user's/distributor's responsibility. Please follow the guidelines below before shipment.

8.3 Guidelines for Returning Unit for Repair

Use the original packaging material if possible when shipping the unit for repair. Otherwise wrap it with bubble pack and use a corrugated box for additional protection. Include a brief description of any faults suspected for the convenience of Customer Service Dept., if possible.

For more information on Eutech Instruments'/ Oakton Instruments' products, contact your nearest distributor or visit our website listed below:

Oakton Instruments P.O Box 5136, Vernon Hills, IL 60061, USA Tel: (1) 888-462-5866 Fax: (1) 847-247-2984 E-mail: info@4oakton.com Web-site: www.4oakton.com	Eutech Instruments Pte Ltd. Blk 55, Ayer Rajah Crescent, #04-16/24 Singapore 139949 Tel: (65) 6778 6876 Fax: (65) 6773 0836 E-mail: marketing@eutechinst.com Web-site: www.eutechinst.com	Distributed by:
---	--	------------------------