


NOTICE

The Extended Burner Assembly discharge plug must be in place during transport to prevent accidental leakage or ignition. Always be certain that the ignitor is completely extinguished.

When transporting your drip torch with the Extended Burner Assembly, it is recommended to remove the Extended assembly and replace the Original assembly into the tank for inverted storage. If the Original assembly is not available, be certain to install the discharge plug in the bottom of the Extended Burner Assembly.



No. 85025

SURE SEAL

www.forestry-suppliers.com