




Z.I. Crolles, 132 rue du Pré Blanc 38920 Crolles, France / Cidex 105 A +33 4 76 92 09 00 / www.petzl.com

Crolles September 12th 2019

Object: Safety information for the harnesses SEQUOIA (C069AA..) and SEQUOIA SRT (C069BA..)

We have been informed about the possible risk of improper mounting the Gated attachment point of the SEQUOIA and SEQUOIA SRT harnesses. No accident have been reported to us. Instructions for use will be updated on as below.



- As a measure of precaution, please check the correct mounting of the two gated attachment points of your SEQUOIA or SEQUOIA SRT.